



EUROKARS HABITAT PTE LTD
27A TANJONG PENJURU, SINGAPORE 609042
ESTIMATE COST OF REPAIRS



Lonpac Insurance Bhd 300 Beach Road, #17-04/07, The Concourse Singapore 199555 ATTN.: MOTOR CLAIMS FAX:		NAME : ADDRESS : TEL :		WIP : 59237 EXCESS : DATE: 30-Sep-22			
VEH NO :	SDD6500R	DATE IN :		CONTACT PERSON :	SHAWN 63310685		
CHASSIS NO :	WMWYS920203J21624	MILEAGE :		TYPE OF CLAIM :	THIRD PARTY		
MODEL :	Cooper S Countryman RHD	DATE REG.:	7-Feb-20	POLICY NO. :			
NATURE OF WORKS							
S/NO	Parts Description			1ST	SUPP	REVISED	PRICES
	QTY						
1	BONNET / <i>DN</i>	1	M41.00.9.626.977				\$ 1,523.28 ✓
2	BONNET HINGE LH X <i>NN</i>	1	M41.00.7.449.379				\$ 143.13
3	BONNET HINGE RH ✓ <i>NN</i>	1	M41.00.7.449.380				\$ 143.13
4	BONNET LOCK LH X <i>NN</i>	1	M51.23.7.300.569				\$ 89.89
5	BONNET LOCK RH ✓ <i>NN</i>	1	M51.23.7.300.570				\$ 89.89
6	HEADLIGHT TRIM RING LH ✓ <i>Ne (ph)</i>	1	M51.71.2.414.967				\$ 65.97 ✓
7	HEADLIGHT TRIM RING RH ✓ <i>AR</i>	1	M51.13.8.739.352				\$ 57.59 ✓
8	EMBLEM FRONT ✓ <i>pk</i>	1	M51.14.7.481.907				\$ 80.53 ✓
9	LABEL, COOLANT ✓ <i>pk</i>	1	M71.23.6.992.810				\$ 32.50 ✓
10	FRONT BUMPER ✓ <i>cut</i>	1	M51.11.7.478.628				\$ 1,080.23 ✓
11	SUPPORT FOGLAMP RH X <i>NN</i>	1	M51.11.7.390.546				\$ 181.16
12	FRONT BUMPER LOWER SPOILER X <i>NN</i>	1	M51.11.7.478.631				\$ 1,027.52
13	TRIM FOR FOGLAMP RH X <i>NN</i>	1	M51.11.7.390.554				\$ 115.25
14	FRONT BUMPER SPONGE X <i>NN</i>	1	M51.64.7.378.723				\$ 68.83
15	FRONT FENDER ARCH RH ✓ <i>cut</i>	1	M51.77.7.475.350				\$ 197.73 ✓
16	ADAPTER FOR FRT FENDER RH ✓ <i>XNN</i>	1	M51.77.7.410.644				\$ 32.76
17	FRONT FENDER RH X <i>NN</i>	1	M41.00.7.449.378				\$ 635.96
18	HEADLIGHT RH ✓ <i>cut</i>	1	M63.11.7.441.316				\$ 3,362.45 ✓
19	ALIGNMENT ELEMENT ✓ <i>X NN</i>	3	M07.14.9.310.339				\$ 35.70
20	MOUNT FOR HEADLIGHT RH ✓ <i>X NN</i>	1	M51.64.7.378.746				\$ 289.51
21	CLIP ✓ <i>pk</i>	1	M51.11.7.490.268				\$ 4.88 ✓
22		0	0				\$ -
TOTAL PARTS							\$ 9,257.89
TOTAL PARTS COST							\$ 9,257.89
SUPPLEMENTARY							
NO	DESCRIPTION	QTY	PARTS NO	1st	Supp	REVISED	PRICES
1							
2							

Labour Description			
1	TO REMOVE & REPLACE BONNET, FRT BUMPER, REINFORCEMENT, FRT FENDER RH & ALL ACCIDENT DAMAGE AREAS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT. 84" x 2	1680 ✓	\$ 2,940.00
2	TO RESPRAY BONNET, FRT BUMPER, FRT FENDER RH 800 x 2	1600 ✓	\$ 2,600.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	150 ✓	\$ 250.00
4	TO INSTALL THE BONNET STICKER.	NETT	\$ 270.00 ✓
5	TO TRANSFER THE FRT BUMPER SENSORS.	150 ✓	\$ 300.00
6	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	150 ✓	\$ 250.00
7	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	250 ✓	\$ 350.00
8	SUNDRIES.	NETT 20 ✓	\$ 50.00

TOTAL LABOUR	\$ -	\$ 7,010.00
TOTAL PARTS	\$ -	\$ 9,257.89
TOTAL	\$ -	\$ 16,267.89
LESS EXCESS	\$ -	-
TOTAL AFTER EXCESS	\$ -	-
GST 7%	\$ -	-
GRAND TOTAL	\$ -	-

REMARKS:

THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.

TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A

QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED

IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

ster (LKK)
5/10/22, 10 am
m IL
5 dji
P/P
My BL Y

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: