

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/CTI22009562/EVY3E2**Date:** 28/12/2022REFERENCEHandling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSNW00112422203

**Claimant Vehicle
No :** SLM5828K**Insured Vehicle
No :** SKQ9079U

Date of Loss: 18/08/2022

Nature of Claim: TP

Claim
No: SNM22D205826/C02/CHNGPWDESCRIPTION & IDENTIFICATION OF VEHICLEReg No: **SLM5828K**

Make & Model: TOYOTA HARRIER, 2.0 (A)

Engine No: 3ZRB975630

Reg. Date: 31/03/2017 (Man. Year: 2017)

Chassis No: ZSU600100650

Colour: Black

Odometer: 87304 km

Engine Capacity: 1986 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/65 R16

Rear Tyre Size: 215/65 R16

Front Left Side: Bridgestone 5 mm

Rear Left Side: Bridgestone 5 mm

Front Right Side: Bridgestone 5 mm

Rear Right Side: Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,674.87	2,859.77	815.10	22.18
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,310.00	1,030.00	280.00	21.37
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,984.87	3,889.77	1,095.10	21.97
Approved Total (Overridden) (S\$)		3,100.00		
(S\$)	4,984.87	3,100.00	1,884.87	37.81
+ GST 7.00/7.00% (S\$)	348.94	217.00	131.94	37.81
Nett Amount (S\$)	5,333.81	3,317.00	2,016.81	37.81

INSPECTION

Date of Assignment: 28/09/2022

Date Inspected: 17/10/2022 Inspected At:

Mova Automotive Pte Ltd (Bukit Merah)
Blk 1008, #01-04/06/08/94, Bukit Merah Lane 3
Singapore 159722

Estimated Period of Repair: 5.0 days

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 28 Dec 2022)
Parts:	M1-SUV	TOYOTA HARRIER 2.0 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLM5828K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOT	Dented	2,544.40 FL	*2,226.40 FL
2	1		*REAR BOOT EMBLEM HARRIER	Necessary	76.80 FL	*76.80 FL
3	1		*REAR BUMPER TOP	Dented	1,580.70 FL	*904.00 FL
4	1		*REAR BUMPER LOWER	Cut	456.80 FL	*456.80 FL
5	1		*REAR BUMPER REFLECTOR LH	Not Necessary	65.10 FL	*- FL
6	1		*REAR BUMPER RETAINER LH	Broken	65.70 FL	*65.70 FL
7	10		*REAR BUMPER CLIPS	Necessary	57.00 FL	*30.00 FL
8	1		*REAR END PANEL (NPA)	Repair	0.00 FL	*- FL
9	1		*REAR FENDER LH (NPA)	Repair	0.00 FL	*- FL
10	1		*REAR WINDSCREEN SEALANT	Necessary	40.00 FS	*40.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	4,886.50	3,799.70
- List Item Discount on L Items 25.00/25.00% (S\$)	1,211.63	939.93
Total Parts (S\$)	3,674.87	2,859.77

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CUT & WELD REAR PANEL .TO REPAIR REAR END PANEL ,REAR FENDER LH ,TO REMOVE & REFIX DAMAGED PARTS ,STRAIGHTEN & REALIGN AFFECTED AREAS	New	500.00	400.00
2	TO SPRAY AFFECTED AREAS ,REAR BOOT ,REAR FENDER LH ,REAR END PANEL ,REAR BUMPER & AFFECTED AREAS	New	750.00	600.00
3	TO REMOVE & REFIX REAR BOOT MECHANISM CHECK & TEST WIPER MOTOR & CENTRE LOCKING SYSTEM	New	60.00	30.00
Gross Labour Cost (\$\$)			1,310.00	1,030.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >