



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

do front bumper

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLN1568G
Chassis No : MRHCR1630GP000119
Model : ACCORD 2.0 AT 2016
Owner's Name : TOKIO MARINE INSURANCE SINGAPORE
Ins Policy No :
Date of Accident : 27/9/2022

Document No. : SQT22002831
Date : 27. Sep 2022
Customer No. : WZF002
Svc Advisor :
Engine No : R20Z21600157
Date | Time : 27. Sep 2022 2:17:43 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:)						
	OWNER:						
	OWNER INSURER:						
	ACC DATE:						
	SURVEYED BY:						
	DATE:						
	REF NO:						
	TP INSURER:						
	TP VEH:						
BO-NUM-COMP-L	NUMBER PLATE WITH CASING-L(N) X NN	1	45.00		45.00	3.15	48.15
39680-T0A-R11ZN	SENSOR ASSYPARKING / cut 2 +	1	94.80	25	284.40	19.91	304.31 142.20
71500-T2M-T80ZZ	FACE ASSYRR.BUMPER / BR	1	630.50	25	472.87	33.10	505.97
33555-T2A-A01	REFLECTOR ASSYL.RR. / ms	1	23.50	25	17.62	1.23	18.85 22.80
71502-T2M-T50	GARNISHRR.BUMPER LOWER / X NN	1	85.80	25	64.35	4.50	68.85
71503-T2M-T50	MOULDINGRR.BUMPER / BR	1	225.70	25	169.27	11.85	181.12
71505-S5A-000	BRACKETR.RR.BUMPER / X NN	1	7.00	25	5.25	0.37	5.62
71555-S5A-000	BRACKETL.RR.BUMPER / X NN	1	5.80	25	4.35	0.30	4.65
71508-T3V-A00	PROTECTORRR.BUMPER SIDE / X NN	1	26.30	25	19.72	1.38	21.10
71530-T2J-H50ZZ	BEAM COMP,RR BPR / BT	1	336.60	25	252.45	17.67	270.12
71593-T2A-A01	SPACERR.RR.BUMPER SIDE / BR	1	14.10	25	10.57	0.74	11.31
71598-T2A-A01	SPACERL.RR.BUMPER SIDE / BR	1	14.10	25	10.57	0.74	11.31
91505-TM8-003	CLIP,BUMPER / 11c 4 +	1	2.30	25	1.72	0.12	1.84 6.90
68500-T2M-Z10ZZ	LID COMPTRUNK / M	1	1011.20	25	758.40	53.09	811.49
74865-T2A-003	WEATHERSTRIPTRUNK LID / X NN	1	82.30	25	61.72	4.32	66.04
75701-T2A-A02	EMBLEMH / 11c	1	30.80	25	23.10	1.62	24.72
75722-T2A-A01	EMBLEMRR.ACCORD / 11c	1	22.20	25	16.65	1.17	17.82
75725-TG2-K00	EMBLEMRR.I-VTEC / 11c	1	39.40	25	29.55	2.07	31.62
65550-T2B-P00ZZ	PAN COMPSPARE TIRE / X NN	1	388.40	25	291.30	20.39	311.69

Printed on 27/9/2022 2:46:10 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.

HONDA

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLN1568G
Chassis No : MRHCR1630GP000119
Model : ACCORD 2.0 AT 2016
Owner's Name : TOKIO MARINE INSURANCE SINGAPORE
Ins Policy No. :
Date of Accident : 27/9/2022

Document No. : SQT22002831
Date : 27. Sep 2022
Customer No. : WZF002
Svc Advisor :
Engine No : R20Z21600157
Date | Time : 27. Sep 2022 2:17:43 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
66100-T2M-U00ZZ	PANEL COMPR. <i>✓ DD</i>	1	465.70	25	349.27	24.45	373.72
84640-T2M-Z01ZA	LINING ASSYRR.PANEL <i>X NN</i>	1	90.10	25	67.57	4.73	72.30
75700-TA0-A00	EMBLEMFR. <i>X NN</i>	1	30.80	25	23.10	1.62	24.72
90301-ST0-003	NUT,PUSH 3MM <i>X NN</i>	1	2.10	25	1.57	0.11	1.68
91501-TR0-003	CLIP,INNER FENDER <i>X NN</i>	9	2.80	25	18.90	1.32	20.22
91505-TM8-003	CLIP,BUMPER <i>X NN</i>	12	2.30	25	20.70	1.45	22.15
34155-T2A-E01	LIGHT ASSYL.LID <i>(LH) - CMT</i>	1	474.00	25	355.50	24.89	380.39
Sum Item					3375.47	236.29	3611.76
BOSUN	SUNDRIES	1	110.00	<i>50 30</i>	110.00	7.70	117.70
BOJSE	BODY JOINT SEALANT.	1	120.00	<i>X</i>	120.00	8.40	128.40
BOBC	BODY UNDERSIDE COATING (N)	1	520.00	<i>X</i>	520.00	36.40	556.40
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	520.00	<i>X</i>	520.00	36.40	556.40
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	250.00	<i>180</i>	250.00	17.50	267.50
BA02R	REMOVE & INSTALL REVERSE SENSORS-4 PCS (N)	1	250.00	<i>180</i>	250.00	17.50	267.50
BC011R	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA	1	650.00	<i>580</i>	650.00	45.50	695.50
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00	<i>80 (part)</i>	650.00	45.50	695.50
BMU30R	REMOVE & INSTALL EXHAUST SYSTEM.(N)	1	650.00	<i>X</i>	650.00	45.50	695.50
BMF00D	RREMOVE & INSTALL FUEL TANK FUEL PIPES.(N)	1	650.00	<i>X</i>	650.00	45.50	695.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	650.00	<i>580</i>	650.00	45.50	695.50
BKOT00R	REMOVE & RENEW RR FLOOR INSULATOR.(N)	1	650.00	<i>X</i>	650.00	45.50	695.50
BKRP02B	CUT & RENEW RR FLOOR PANEL.CUT LH FENDERS ALIG <i>4 X 650</i>	1	4000.00	<i>1700 2600</i>	4000.00	280.00	4280.00
BP07R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (7P) <i>5 X 500</i>	1	3500.00	<i>1500 2600</i>	3500.00	245.00	3745.00
BO-TOW	TOWING SERVICES (MBBS)	1	150.00	<i>/</i>	150.00	10.50	160.50
Sum Labor					13320.00	932.40	14252.40

Survey By

Printed on 27/9/2022 2:46:10 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : MS FIRST CAPITAL INSURANCE LIMITED
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLN1568G
Chassis No : MRHCR1630GP000119
Model : ACCORD 2.0 AT 2016
Owner's Name : TOKIO MARINE INSURANCE SINGAPORE
Ins Policy No. :
Date of Accident : 27/9/2022

Document No. : SQT22002831 **Page** 3
Date : 27. Sep 2022
Customer No. : WZF002
Svc Advisor :
Engine No : R20Z21600157
Date | Time : 27. Sep 2022 2:17:43 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Item	Description	Qty	Unit Price	Disc %	Amount	7% GST Amount	Amount incld GST
Date & Time	28/9/22, 4:00p				Total Amount	16,695.47	1,168.69
Excess	Stn CLKK				Total (Inclusive of GST)		17,864.16
Status							
Signature	P/P						

by BL cy
8 - 5 dyr

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 27/9/2022 2:46:10 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

An amount of \$53.50 (incl GST) will be applicable for the request of the above quotation for estimates above \$2,000.00.

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 7% to 8% with effect from 1st Jan 2023.