



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22009571/Kny3q2 Date: 18/10/2022	Code: AGI
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
<b>Insured Veh.</b>	SLP 6677G	<b>Veh. Inspected</b>	SKV 4451J	
<b>Policy No.</b>	P10740167R00	<b>Coverage (\$)</b>	0.00	
<b>Claim No.</b>	C10017716/JM	<b>Excess (\$)</b>	0.00	
<b>Assign From</b>	SALIZAWATI HAIZAR	<b>Assign Date</b>	28/09/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
<b>Make &amp; Model</b>	SUBARU FORESTER (A)	<b>c.c</b>	1998	
<b>Engine No.</b>	HIDDEN	<b>Year of Reg.</b>	2015	
<b>Chassis No.</b>	JF1SJGK85FG054349	<b>Colour</b>	METALLIC RED	
<b>Odometer</b>	123526 KM	<b>Steering</b>	IN ORDER	
<b>Brakes</b>	IN ORDER	<b>Modification</b>	SPORTS RIM	
<b>General</b>	GOOD			
<b>3. Conditions of Tyres</b>				
	<b>Size</b>	<b>Make</b>	<b>Balance</b>	
<b>R/H Front Tyre</b>	235/50 R18	GOODYEAR	6 mm	
<b>L/H Front Tyre</b>	235/50 R18	GOODYEAR	6 mm	
<b>R/H Rear Tyre</b>	235/50 R18	GOODYEAR	6 mm	
<b>L/H Rear Tyre</b>	235/50 R18	GOODYEAR	6 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
<b>Accident Date</b>	24/09/2022	<b>Inspection Date</b>	28/09/2022	
<b>Survey held at</b>	LM AUTO SOLUTION PTE LTD BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C #01-12, SINGAPORE 575645			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
<b>ESTIMATED NORMAL PERIOD FOR REPAIR:</b>		<b>5 Working Days</b>		