



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

NO. : 41704

DATE : 26/09/2022
CLAIM NO. : 12008
POLICY NO. : 5103867826-03
FROM : RAYMOND

VEHICLE NO. : FC3311X
MAKE/MODEL : YAM / SUPER TENERE

not Ailbom
run
2/5 @ 4100
4 days
28/09/22
teknik Ailbom

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BOLT P/N: 46879 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$4.00	4.00
2	BOX REAR YAMAHA P/N: 74892 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,175.00	1,175.00
3	BOX SIDE LH (ALUMINIUM SILVER) P/N: 66713 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,170.00	1,170.00
4	BRACKET HANDLE P/N: 45243 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$12.00	12.00
5	BRACKET HANDLE 3 P/N: 45244 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$9.00	9.00
6	COVER 1 SPARK - (REPORTED BY MECHANIC)	Repair	1.00	\$49.00	49.00
7	COVER HANDLE LH P/N: 54372 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$33.00	33.00
8	EMBLEM P/N: 45253 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$48.00	48.00
9	FOOTREST FRONT LH P/N: 46861 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$54.00	54.00

*41704 *

bizSAFE₃



S/N	Description	Action	Qty	Unit Price	Amount
10	GEAR LEVER RUBBER MONSTER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$21.00	21.00 <i>su</i>
11	GUARD ENGINE (1SET) P/N: 54375 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$1,064.00	1,064.00 <i>cu</i>
12	HOLDER P/N: 74891 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$42.00	42.00 <i>eng</i>
13	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install <i>x</i>	8.00	\$63.00	504.00 <i>380</i>
14	LED LIGHT PIAA - (REPORTED BY MECHANIC)	REPLACE	1.00	\$2,100.00	2,100.00 <i>su</i>
15	LEVER CLUTCH P/N: 46841 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$127.00	127.00 <i>su</i>
16	MIRROR LH P/N: 46826 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$98.00	98.00 <i>520</i>
17	NUT SPRING P/N: 45260 - (REPORTED BY MECHANIC)	REPLACE	6.00	\$1.50	9.00 <i>ner</i>
18	PANEL 1 SPARY - (REPORTED BY MECHANIC)	REPLACE	1.00	\$49.00	49.00 <i>17</i>
19	PANEL 2 P/N: 45261 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$216.00	216.00 <i>17</i>
20	PLATE BASE STAND SIDE P/N: 74893 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$133.00	133.00 <i>cu</i>
21	POWDER COAT CRASH BAR SET P/N: 65664 - (REPORTED BY MECHANIC) UPPER CRASH BAR	Repair <i>x</i>	1.00	\$220.00	220.00 <i>LR</i>
22	REAR FOOTREST ASSY 1 P/N: 73673 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$14.00	14.00 <i>cu</i>
23	SPARY TANK - (REPORTED BY MECHANIC)	REPLACE <i>x</i>	1.00	\$210.00	210.00 <i>labour</i>
24	SPRAY PAINT SIDE BOX TO BLACK - (REPORTED BY MECHANIC)	Repair <i>x</i>	1.00	\$170.00	170.00 <i>labour</i>

*41704 *

bizSAFE₃

S/N	Description	Action	Qty	Unit Price	Amount
25	STAND SIDE P/N: 56727 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$210.00	210.00
26	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$19.00	19.00
27	TAPE CRASH BAR BLACK CARBON P/N: 74364 - (REPORTED BY MECHANIC)	REPLACE	5.00	\$21.00	105.00
28	TRANSPORT CHARGES (MOTORCYCLE) OVERSIZED P/N: 45837 - ONE WAY TOWING		1.00	\$85.00	85.00
29	WINDSHIELD GIVI P/N: 74894 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$265.00	265.00

SUB TOTAL

\$8,215.00

GST @ 7 %

\$575.05

GRAND TOTAL (SGD)

\$8,790.05

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of

BAN HOCK HIN CO PTE LTD



RAYMOND

Acknowledge & Accepted By

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*41704 *

bizSAFE₃CERT NO.: 2002-1-0383
ISO 9001:2015