

S3 AUTO WORKSHOP

ADDRESS: 2 KAKI BUKIT AVENUE 2 AUTOHUB #01-14 SINGAPORE 417921

MOBILE: +65 84404430 - MR LIEW (AH GUO)

ESTIMATED REPAIR CHECKLIST

TO :	VEHICLE REGISTRATION NO.:	SGC8949L
ATTENTION : MOTOR INSURANCE CLAIM	VEHICLE MAKE/MODEL:	LEXUS GS200T EXECUTIVE
CLAIM TYPE : 3RD PARTY CLAIM	CHASSIS NUMBER:	JTHBA1BL10A0008
ACCIDENT DATE/TIME :		

NO.	PARTS	QTY	First survey	Disputed	Final	LIST PRICE
1	BOOTLID	1	Dent	/R	R	\$ 1,021.30 X R
2	BOOTLID CENTRE EMBLEM	1	X	X NN		\$ 70.32 X
*3	BOOTLID LOCK	1	Cut	X NC		\$ 1,207.20 ? den
4	REAR BUMPER	1	BR	/		\$ 913.27 cra
5	REAR BUMPER LH SIDE REVERSE SENSOR	1	cra	/	300	\$ 422.18 cra
6	REAR BUMPER LH CENTRE REVERSE SENSOR	1	cra	/	300	\$ 422.18 den
7	REAR BUMPER REVERSE SENSOR HOLDERS	4	X	X NN		\$ 168.00 X
8	REAR BUMPER LOWER GARNISH	1	cra	/	510	\$ 563.10 ?
9	REAR BUMPER LH REFLECTOR	1	cra	/		\$ 68.90 ?
10	REAR BUMPER RH SIDE RETAINER	1	X	X NN		\$ 98.00 ? X
11	REAR BUMPER LH SIDE RETAINER	1	cra	/		\$ 98.80 ?
12	REAR BUMPER RH SIDE SUPPORT BRACKET	1	X	X NN		\$ 101.31 ? X
13	REAR BUMPER LH SIDE SUPPORT BRACKET	1	cra	/	95	\$ 101.31 ?
14	REAR BUMPER LH EXHAUST CHROME FINISHER	1	Dent	/	300	\$ 341.60 den
15	REAR BUMPER INNER SPONGE	1	BR	/		\$ 151.60 ?
16	REAR BUMPER REINFORCEMENT	1	Dent	/	470	\$ 511.20 ?
17	LH TAILLAMP ASSY	1	crack	/		\$ 903.10 ?
18	LH TAILLAMP SIDE GARNISH	1	X	X NN		\$ 125.71 den
19	END PANEL	1	Dent	R	R	\$ 893.67 ? X R D
20	END PANEL INNER GARNISH	1	X	X NN		\$ 455.10 ?
21	EXHAUST SILENCER LH	1	Dent	/R	R	\$ 1,221.07 ? Denx
22	EXHAUST SILENCER GASKET LH	1	X	X NN		\$ 65.00 X
23	REAR LH FENDER INNER TRIM	1	X	X NN		\$ 482.65 ? X
24	REAR SPARE TYRE COVER BOARD	1	X	X NN		\$ 405.56 ? X
25	REAR Left sensor detector (Blindspot)	1	cra	/	1350	\$ (2119.60)
26	REAR Left					
SUBTOTAL :						\$ 10,911.01 5450
LESS 10% :						\$ 1,091.10 545
PARTS TOTAL :						\$ 9,819.91 4905

NO.	PARTS	QTY	SPECIAL NETT PRICE
1	BOOTLID INNER TRIM CLIPS	1SET	\$ 80.00 ? X
2	END PANEL INNER GARNISH CLIPS	1SET	\$ 60.00 ? X
3	END PANEL JOINT SEALANT	1	\$ 80.00 ? X
4	REAR LH FENDER INNER TRIM CLIPS	1SET	\$ 80.00 ? X
5	REAR BUMPER CLIPS	1SET	\$ 85.00 / 40

NO. LABOUR CHARGES

AMOUNT

5 days L/S
29/09/22 3pm

1rfan
a n n a n h a

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

SPECIAL NETT TOTAL : \$

385.00 40

1	CUT/WELD, PANEL BEATING, STRAIGHTEN AND ALIGNMENT AFFECTED PARTS AND AREAS. TO REMOVE, REPLACE AND CHECK PARTS.	\$	1,200.00	600
2	PUTTY, SAND DOWN AND RE-SPRAY AFFECTED AREAS AND PARTS ON THE AFFECTED AREAS	\$	1,200.00	400
3	CHECK AND TEST WIRING SYSTEM AND LIGHTING SYSTEM	\$	80.00	2050
4	APPLY ANTI-RUST COATING ON REPLACED AND REPAIRED PARTS AND AREAS	\$	100.00	X
5	REMOVE AND REINSTALL REAR REVERSE CAMERA TO ASSIST REPAIR	\$	180.00	30
6	REMOVE AND REINSTALL BOOTLID INNER MECHANISM TO NEW BOOTLID	\$	180.00	30
7	REMOVE AND REPLACE REAR BUMPER REVERSE SENSORS TO ASSIST REPAIR	\$	100.00	30
8	REMOVE AND REPLACE REAR INNER TRIMS AND GARNISH TO ASSIST REPAIR	\$	320.00	X
9	REMOVE AND REPLACE EXHAUST SILENCER AND GASKET TO ASSIST REPAIR	\$	220.00	80

LABOUR TOTAL: \$ 3,580.00 (220)

LIST PRICE:	\$	9,819.91	4905
SPECIAL NETT:	\$	385.00	40
LABOUR:	\$	3,580.00	1220
TOTAL:	\$	13,784.91	20% = 1233

= 6165
Aft 20% = 4930