



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMD 6316A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	RH REAR DOOR	TO REPAIR SEE LABOUR	2,925.96	-
1	RH REAR DOOR SEAL	NOT NECESSARY	360.68	-
	LESS 10% DISCOUNT		-328.66	-
			2,957.98	-
	<u>SPECIAL NETT ITEMS</u>			
1	REAR RH RIM (SN)	SCRATCHED	180.00	180.00
1	SUNDRIES (SN)	NECESSARY	37.50	30.00
			217.50	210.00
	<u>LABOUR</u>			
	TUFF KOTE.	NOT NECESSARY	25.00	-
	REMOVE AND REFIT/PANEL-BEAT RH REAR DOOR, SEAL, FENDER, BUMPER AND OTHER ASSOCIATE COMPONENTS. INCLUSIVE OF THE REPAIR OF RH REAR DOOR.		500.00	500.00
	SURFACE PREPARATION, SPRAY PAINT AND POLISH RH REAR DOOR, FENDER, BUMPER AND OTHER AFFECTED AREAS.		750.00	600.00
	DIAGNOSTIC CHECK AND ERASE FAULT CODES AFTER THE REPAIR.		80.00	80.00
			1,355.00	1,180.00
	GRAND TOTAL		4,530.48	1,390.00
	RECOMMENDED COST OF REPAIRS			1,390.00

Report Ref No. CS/SMR22009575/Tqy3m4

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ANG BRYAN TANI

Automotive Assessor / Investigator

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.