

Repair Estimate

VAG Singapore Pte Ltd

48 Toh Guan Road East

#05-136, Enterprise Hub

Singapore 608586

Tel: 6267 9916

Fax: 6267 9313

www.avantage.sg

Date : 27-Sep-2022

Vehicle Num : SMD6316A

Make/Model : Seat Ibiza 5DR 1.00 TSI 116

Chassis No : VSSZZKJZJR133700

S/N	PARTS	QTY	PRICE	TOTAL
1	RH Rear Door	1	\$ 2,925.96	
2	RH Rear Door Seal	1	\$ 360.68	
	TOTAL PARTS			\$ -
	Less 10%			
	TOTAL AMOUNT			\$ -
	MISCELLANEOUS ITEM			
1	Sunderies		\$ 37.50	\$ 30.00
2	Tuff Kote		\$ 25.00	
	LABOUR			
1	Remove and refit/Panel-beat RH Rear Door, Seal, Fender, Bumper and other associate components.		\$ 500.00	\$ 500.00
2	Surface preparation, spray paint and polish RH Rear Door, Fender, Bumpere and other affected areas.		\$ 750.00	\$ 600.00
3	Diagnostic check and erase fault codes after the repair.		\$ 80.00	\$ 80.00
4	Refurbish RH Rear Wheel/Rim		\$ 180.00	\$ 180.00
	TOTAL			\$ 1,390.00
	GST 7%			\$ 97.30
	GRAND TOTAL			\$ 1,487.30