

FINALIZE COST OF REPAIRS

EQ INSURANCE COMPANY LTD		NAME :				WIP :		31685			
5 Maxwell Road		ADDRESS :				DATE:		17-Mar-23			
#17-00 Tower Block											
MND Complex, Singapore 069110											
ATTN. : MOTOR CLAIMS		TEL :									
VEH NO :	SKN9447G	DATE IN :				CONTACT PERSON :	JESS				
CHASSIS NO :	JM6BM42A8E0132420	MILEAGE :				TYPE OF CLAIM :	THIRD PARTY CLAIM				
MODEL :	MAZDA 3	DATE REG.:	31-Jul-14								
NATURE OF WORKS											
NO	DESCRIPTION				QTY	UNIT PRICE	1st	Supp	PARTS NO	REVISED	PRICES
1	REAR BUMPER				1	1,143.51			MBPD8-50-221ABB	1,143.51	1,047.30
2	LHS CENTER BRACKET,BUMPER				1	26.30			MBHR2-50-251A		24.90
3	RHS CENTER BRACKET,BUMPER				1	4.64			MDFR5-50-251		5.40
4	RETAINER(R),REAR BUMPER				1	40.55			MBHN1-50-2H1A		38.00
5	RETAINER(L),REAR BUMPER				1	40.55			MBHN1-50-2J1A		38.00
6	LHR BUMPER EDGE BRACKET'B'				1	51.17			MBHN9-51-077B		47.90
7	RHS BUMPER EDGE BRACKET'A'				1	51.17			MBHN9-51-067B		47.90
8	RIVET				4	3.71			MBBM4-50-355	14.84	18.00
9	RHR REFLECTOR				1	55.13			MD350-51-5M0E		53.00
10	LHR REFLECTOR				1	55.13			MD350-51-5L0E		53.00
11	FASTENER				4	2.36			MB45A-56-146A	9.44	12.00
12	TAPE				3	7.42			MGS1D-50-EM1A	22.26	25.80
13	SENSOR,ULTRASONIC				4	184.59			MKD47-67-UC1 27		814.40
14	SENSOR RETAINER				4	15.77			MKD47-67-UC5A27		72.80
15	SENSOR WIRE				1	189.14			MBHR1-67-290		160.70
16	LHR TOWING COVER				1	14.84			MBHN1-50-EL1 BB	14.84	16.50
17	RHR TOWING COVER				1	14.84			MBHN1-50-EK1 BB		17.10
18	BEAM,REAR BUMPER				1	576.77			MB45A-50-260	576.77	564.20
19	RHS TAIL LAMP GASKET,OUTER				1	26.47			MBHN1-51-153	26.47	22.00
20	LHS TAIL LAMP GASKET,OUTER				1	26.47			MBHN1-51-163	26.47	22.00
21	RHS TAIL LAMP GASKET-TRUNK LID				1	26.47			MB45A-51-3H8		22.00
22	LHS TAIL LAMP GASKET-TRUNK LID				1	26.47			MB45A-51-3J8		22.00
23	ORNAMENT,CAR NAME-MAZDA 3				1	59.76			MBHN1-51-721		56.10
24	MASCOT,REAR				1	71.65			MBHN1-51-730		78.20
25	ORNAMENT,SKYACTIV				1	84.04			MBHN1-51-771		66.80
									TOTAL PARTS	1,834.60	3,346.00
										-	
									TOTAL PARTS COST	1,834.60	3,346.00
Labour Description											

			REVISED	PRICES	
1		M3 UBI REPLACE REAR BUMPER. PO42948 / SUBLET 12861	660.00	1,980.00	
2		RESPRAY REAR BUMPER. PO42948 / SUBLET 12861	630.00	1,890.00	
3	MZ-BR-REVSEN	TRANSFER REVERSE SENSORS. PO42948 / SUBLET 12861	180.00	660.00	
4	MZ-BR-SPOILER	TO REMOVE & REFIX SPOILER TAILGATE		660.00	
5	MZ-BR-ELECTR	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTION. PO42948 / SUBLET 12861	120.00	200.00	
6	MZ-BR-REPROG	TO REPROGRAM AFTER THE ACCIDENT REPAIRS. PO42948 / SUBLET 12861	150.00	250.00	
7	MZ-BR-CAVITY	TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU)		250.00	
8	MZ-BR-SUNDRI	SUNDRIES. PO42948 / SUBLET 12861	20.00	50.00	
REMARKS: THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A QUOTATION FEE OF \$400 WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.			TOTAL LABOUR	1,760.00	5,940.00
			TOTAL PARTS	1,834.60	3,346.00
			TOTAL	3,594.60	9,286.00
			LESS EXCESS	-	-
			TOTAL AFTER EXCESS	3,594.60	
			GST 7%	251.62	-
			GRAND TOTAL	3,846.22	-

TRANS EUROKARS PTE LTD

 Authorised Signature