

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

EQ INSURANCE COMPANY LTD

5 MAXWELL ROAD #17-00 TOWER BLOCK MND COMPLEX

SINGAPORE 069110

INV No. AC2302322

INV Date 14/04/2023

Reference CS/EQI22009576/Uqy3e2

Code EQI

PROFESSIONAL SERVICE FEE

Vehicle No. SKN 9447G

Insured Veh. YP 3718M

Claim No. DM22HO01558

Policy No. DMCHHQ22-000110

Accident Date 09/09/2022

Inspection Date 03/10/2022

Description	Total
Survey Inspection	160.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Subtotal	160.00
GST (8%)	12.80
Grand Total	172.80

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

		Affiliated to Federation Internation	nale Des Experts En Automo	bile
	EQ INSURANCE C	COMPANY LTD	Ref:	CS/EQI22009576/Uqy3e2
	5 MAXWELL ROAI #17-00 TOWER BL MND COMPLEXSI		Date:	14/04/2023
			Code:	EQI
1.		Policy Particulars	:- THIRD PARTY CLAIN	Л
	Insured Veh.	YP 3718M	Veh. Inspected	SKN 9447G
	Policy No.	DMCHHQ22-000110	Coverage (\$)	0.00
	Claim No.	DM22HO01558	Excess (\$)	0.00
	Assign From	NEO JIE SI	Assign Date	28/09/2022
2.		Vehicle Partic	culars & Condition	
	Make & Model	MAZDA 3 (A)	c.c	1496
	Engine No.	HIDDEN	Year of Reg.	2014
	Chassis No.	JM6BM42A8E0132420	Colour	GREY
	Odometer	108620 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3.	3. Conditions of Tyres			
		Size	Make	Balance
	R/H Front Tyre	205/60 R16	YOKOHAMA	7 mm
	L/H Front Tyre	205/60 R16	YOKOHAMA	7 mm
	R/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm
	L/H Rear Tyre	205/60 R16	YOKOHAMA	7 mm
4.	. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.			
	DAMAGES SEE D	ETAILS.		
5.		Genera	I Information	
	Accident Date	09/09/2022	Inspection Date	03/10/2022
	Survey held at	TRANS EUROKARS PTE LTD		
		NO 5 UBI CLOSE SINGAPORE 408605		
5a.			emarks	
		ON WAS CONDUCTED ON A"WIT CE TO YOUR INSTRUCTIONS, W		
5b.		Estimate	Days of Repair	
	ESTIMATED NOR	MAL PERIOD FOR REPAIR:	3 Work	ing Days
	-		'	



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKN 9447G

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER	TORN	1,143.51	1,143.51
1	LHS CENTER BRACKET, BUMPER	NOT NECESSARY	24.90	-
1	RHS CENTER BRACKET, BUMPER	NOT NECESSARY	5.40	-
1	RETAINER(R), REAR BUMPER	NOT NECESSARY	38.00	-
1	RETAINER(L), REAR BUMPER	NOT NECESSARY	38.00	-
1	LHR BUMPER EDGE BRACKET 'B'	NOT NECESSARY	47.90	-
1	RHS BUMPER EDGE BRACKET 'A'	NOT NECESSARY	47.90	-
4	RIVET @\$4.50	NECESSARY	18.00	14.84
1	RHR REFLECTOR	NOT NECESSARY	53.00	-
1	LHR REFLECTOR	NOT NECESSARY	53.00	-
4	FASTENER @\$3.00	NECESSARY	12.00	9.44
3	TAPE @\$8.60	NECESSARY	25.80	22.26
4	SENSOR, ULTRASONIC @\$203.60	NOT NECESSARY	814.40	-
4	SENSOR RETAINER @\$18.20	NOT NECESSARY	72.80	-
1	SENSOR WIRE	NOT NECESSARY	160.70	-
1	LHR TOWING COVER	TORN	16.50	14.84
1	RHR TOWING COVER	NOT NECESSARY	17.10	-
1	BEAM, REAR BUMPER	DENTED	576.77	576.77
1	RHS TAIL LAMP GASKET, OUTER	NECESSARY	26.47	26.47
1	LHS TAIL LAMP GASKET, OUTER	NECESSARY	26.47	26.47
1	RHS TAIL LAMP GASKET-TRUNK LID	NOT NECESSARY	22.00	-
1	LHS TAIL LAMP GASKET - TRUNK LID	NOT NECESSARY	22.00	-
1	ORNAMENT, CAR NAME-MAZDA 3	NOT NECESSARY	56.10	-
1	MASCOT, REAR	NOT NECESSARY	78.20	-
1	ORNAMENT, SKYACTIV	NOT NECESSARY	66.80	-
			3,463.72	1,834.60
	SPECIAL NETT ITEMS			
1	SUNDRIES (SN)	NECESSARY	50.00	20.00
			50.00	20.00
1	I	I		

Report Ref No. CS/EQI22009576/Uqy3e2



RECOMMENDED COST OF REPAIRS

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

3,594.60

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	LABOUR			
	TO REPLACE REAR BUMPER & TAIL GATE.		1,980.00	660.00
	TO SPRAY PAINT ON REAR BUMPER.		1,890.00	630.00
	TO TRANSFER REVERSE SENSORS.		660.00	180.00
	TO REMOVE & REFIX SPOILER TAILGATE.	NOT NECESSARY	660.00	-
	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		200.00	120.00
	TO REPROGRAMME AFTER RHE ACCIDENT REPAIR WORKS.		250.00	150.00
	TO CARRY-OUT BODY CAVITY PRESERVATION. (INCLUDING NEW PARTS AND CAOUTCHOUC).	NOT NECESSARY	250.00	-
			5,890.00	1,740.00
	GRAND TOTAL		9,403.72	3,594.60

Report Ref No. CS/EQI22009576/Uqy3e2

CHUA KANG SENG

Licensed Appraiser

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

- 4. The issue and acceptance of this is form by instrained companies.
 5. Any false reporting may be referred to the Police for investigation.
 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 12/09/2022 14:29 (SGT) Reported by Date of Accident 09/09/2022 07:58 (SGT) Exact Location of Accident Singapore Additional Location Information PIE CHANGI AIRPORT PAYA LEBAR EXIT, TURNING ONTO PAYA LEBAR RD Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Mazda

1500

Vehicle Registration Number SKN9447G

INSURED/POLICYHOLDER

Is company? Name Of Registered Owner Mr Na Hsi-Chung NRIC No S8990078F Email Address nahsichung@hotmail.com Mobile Phone No (Phone) +65-94507711 Alternative Phone No

VEHICLE PARTICULARS

Model Variant Exact purpose for which vehicle was being used at time of accident Private use Are you claiming under your own insurance policy for repair to your vehicle? No - Claiming third party Vehicle Category Private car Transmission Auto

Manufacturer

INSURANCE COMPANY

Name of Insurance Company AIG Asia Pacific Insurance Pte. Ltd. Policy Number / Cover Note Number

DRIVER

CC

Name of Driver Mr Na Hsi-Chung NRIC No S8990078F Date Of Birth 04/04/1989

Occupation Date Of Driving Pass Driving experience Gender Mobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	Indoor 29/09/2008 14 YEARS Male (Phone) +65-94507711 - nahsichung@hotmail.com 145 Jalan Kampong Chantek - 587880 Yes - No
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collision - Head to Rear Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? Translator's name Translator's ID Translator's phone number Translator's email Original language used in the statement	No 2 No - Yes 2 No
Name Gender	NA HSI-EN Female
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom?	No No -
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKETCH PLAN	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Reasons for not uploading a video of the accident	
DETAILS OF OTHER	VEHICLE PROPERTY 1

YP3718M

Vehicle Registration Number
Vehicle Manufacturer

Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Commercial vehicle
Name of Driver	KENNY LIEW YONG ZHI
NRIC No	S9382390G
Contact Number	(Phone) +65-94223350
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

- Please report <u>correctly</u> the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Actual Driver
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Traffic Police Department for investigation.

- 6. This report will be forwarded by the insurers to the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) investigating the accident and/or my claims:
- (iii) carrying out and/or dealing with my instructions or responding to any enquines by me.
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes, and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their thirp-party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of above Purposes

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date

Sketch Plan

SENHART G 1 3718 M

1

and, Lorry FOR IT 3715 M Will the	Proport and Stopping to thin unto Poya Leber t sear oil Skovale476. Neather was clear and
tord day, Oriver of Sewage Ta as	of not adjustly stop to governily slowed down
to thech for an coming tenthic on You	an letter found
2222	20 5 W 3 1 5 7 7 9
	76
claration	veci alalar
e declare the foregoing particulars are true in every response.	ect / V
4	/ 1 ~
0.000	
a serrou	4 1 1 1 1



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 9447G

INSPECTION















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315















51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315





51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 9447G

RE-INSPECTION







51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

PHOTOGRAPHS FOR VEHICLE NO. SKN 9447G

RE-INSPECTION





