

(08/11/13) wef

ASS. REC. BY: *marcus*

REF:

CS/5Q122009576/4943

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No:

SKN 94476

Yr Regn:

31/07/14

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

made 3

c.c

1496

Colour:

grey

A/C: Insured / Std / NI / NA

Sp. Reading

108620

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM 63M 42A8E0132420

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

7

mm

L/Bal.

7

mm

L/Bal.

7

mm

D.O.A.

09/09/22

D.O.I.

03/10/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

13/4/23 PIP @ 3594.60 in hand less (Red @ 5809.12, 627.7)

Date/Time, File Pass to?

☐

Preli. Report

1) 13/4 14:00

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

3

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

) S + RS. SI

) Photos

) Others

Report Format :

TP

Lump Sum T.I.B.I. (\$

3594.60

TOTAL

P1783594-60

not Adherent  
her maxims  
3/10/22  
Teluk M. Sekupahy.  
3 days.

|                               |              |           |       |           |
|-------------------------------|--------------|-----------|-------|-----------|
| EQ INSURANCE COMPANY LTD      |              | NAME :    | WIP : | 31685     |
| 5 Maxwell Road                |              | ADDRESS : |       |           |
| #17-00 Tower Block            |              |           | DATE: | 23-Sep-22 |
| MND Complex, Singapore 069110 |              |           |       |           |
| ATTN. :                       | MOTOR CLAIMS | TEL :     |       |           |

|              |                   |           |                  |                   |
|--------------|-------------------|-----------|------------------|-------------------|
| VEH NO :     | SKN9447G          | DATE IN : | CONTACT PERSON : | JESS              |
| CHASSIS NO : | JM6BM42A8E0132420 | MILEAGE : | TYPE OF CLAIM :  | THIRD PARTY CLAIM |
| MODEL :      | MAZDA 3           | DATE REG  | 31-Jul-14        |                   |

NATURE OF WORKS

| NO | DESCRIPTION                    | QTY | UNIT PRICE | 1st | Supp | PARTS NO        | REVISED | PRICES   |
|----|--------------------------------|-----|------------|-----|------|-----------------|---------|----------|
| 1  | REAR BUMPER                    | 1   | 1,047.30   |     |      | MBPD8-50-221ABB | 114351  | 1,047.30 |
| 2  | LHS CENTER BRACKET, BUMPER     | 1   | 24.90      |     |      | MBHR2-50-251A   | 11      | 24.90    |
| 3  | RHS CENTER BRACKET, BUMPER     | 1   | 5.40       |     |      | MDFR5-50-251    | 11      | 5.40     |
| 4  | RETAINER(R), REAR BUMPER       | 1   | 38.00      |     |      | MBHN1-50-2H1A   | 11      | 38.00    |
| 5  | RETAINER(L), REAR BUMPER       | 1   | 38.00      |     |      | MBHN1-50-2J1A   | 11      | 38.00    |
| 6  | LHR BUMPER EDGE BRACKET 'B'    | 1   | 47.90      |     |      | MBHN9-51-077B   | 11      | 47.90    |
| 7  | RHS BUMPER EDGE BRACKET 'A'    | 1   | 47.90      |     |      | MBHN9-51-067B   | 11      | 47.90    |
| 8  | RIVET                          | 4   | 4.50       |     |      | MBBM4-50-355    | 14.84   | 18.00    |
| 9  | RHR REFLECTOR                  | 1   | 53.00      |     |      | MD350-51-5M0E   | 11      | 53.00    |
| 10 | LHR REFLECTOR                  | 1   | 53.00      |     |      | MD350-51-5L0E   | 11      | 53.00    |
| 11 | FASTENER                       | 4   | 3.00       |     |      | MB45A-56-146A   | 9.44    | 12.00    |
| 12 | TAPE                           | 3   | 8.60       |     |      | MGS1D-50-EM1A   | 22.26   | 25.80    |
| 13 | SENSOR, ULTRASONIC             | 4   | 203.60     |     |      | MKD47-67-UC1 27 | 11      | 814.40   |
| 14 | SENSOR RETAINER                | 4   | 18.20      |     |      | MKD47-67-UC5A27 | 11      | 72.80    |
| 15 | SENSOR WIRE                    | 1   | 160.70     |     |      | MBHR1-67-290    | 11      | 160.70   |
| 16 | LHR TOWING COVER               | 1   | 16.50      |     |      | MBHN1-50-EL1 BB | 14.84   | 16.50    |
| 17 | RHR TOWING COVER               | 1   | 17.10      |     |      | MBHN1-50-EK1 BB | 11      | 17.10    |
| 18 | BEAM, REAR BUMPER              | 1   | 564.20     |     |      | MB45A-50-260    | 576.77  | 564.20   |
| 19 | RHS TAIL LAMP GASKET, OUTER    | 1   | 22.00      |     |      | MBHN1-51-153    | 26.47   | 22.00    |
| 20 | LHS TAIL LAMP GASKET, OUTER    | 1   | 22.00      |     |      | MBHN1-51-163    | 26.47   | 22.00    |
| 21 | RHS TAIL LAMP GASKET-TRUNK LID | 1   | 22.00      |     |      | MB45A-51-3H8    | 11      | 22.00    |
| 22 | LHS TAIL LAMP GASKET-TRUNK LID | 1   | 22.00      |     |      | MB45A-51-3J8    | 11      | 22.00    |
| 23 | ORNAMENT, CAR NAME-MAZDA 3     | 1   | 56.10      |     |      | MBHN1-51-721    | 11      | 56.10    |
| 24 | MASCOT, REAR                   | 1   | 78.20      |     |      | MBHN1-51-730    | 11      | 78.20    |
| 25 | ORNAMENT, SKYACTIV             | 1   | 66.80      |     |      | MBHN1-51-771    | 11      | 66.80    |

SUPPLEMENTARY

| NO | DESCRIPTION | QTY | UNIT PRICE | 1st | Supp | PARTS NO | REVISED | PRICES |
|----|-------------|-----|------------|-----|------|----------|---------|--------|
| 1  |             |     |            |     |      |          |         |        |

|  |  |                  |  |          |
|--|--|------------------|--|----------|
|  |  | TOTAL PARTS      |  | 3,346.00 |
|  |  |                  |  |          |
|  |  | TOTAL PARTS COST |  | 3,346.00 |

#### Labour Description

|   |               |                                                                           | REVISED | PRICES   |
|---|---------------|---------------------------------------------------------------------------|---------|----------|
| 1 |               | TO REPLACE REAR BUMPER & TAIL GATE                                        | 660     | 1,980.00 |
| 2 |               | TO SPRAY PAINT ON REAR BUMPER & TAIL GATE                                 | 630     | 1,890.00 |
| 3 | MZ-BR-REVERSE | TO TRANSFER REVERSE SENSORS.                                              | 180     | 660.00   |
| 4 | MZ-BR-SPOILER | TO REMOVE & REFIX SPOILER TAILGATE                                        | in X    | 660.00   |
| 5 | MZ-BR-ELECTR  | TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.                        | 120     | 200.00   |
| 6 | MZ-BR-REPROG  | TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.                           | 150     | 250.00   |
| 7 | MZ-BR-CAVITY  | TO CARRY-OUT BODY CAVITY PRESERVATION.(INCLUDING NEW PARTS AND CAOUTCHOU) | in X    | 250.00   |
| 8 | MZ-BR-SUNDR   | SUNDRIES.                                                                 | in 20   | 50.00    |

#### SUPPLEMENTARY LABOUR DESCRIPTION

|   |  |      |  |  |
|---|--|------|--|--|
| 1 |  | #N/A |  |  |
|---|--|------|--|--|

REMARKS:  
THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT. TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A **QUOTATION FEE OF \$400** WILL BE APPLIED ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.

|                    |   |          |
|--------------------|---|----------|
| TOTAL LABOUR       | - | 5,940.00 |
| TOTAL PARTS        | - | 3,346.00 |
| TOTAL              | - | 9,286.00 |
| LESS EXCESS        | - | -        |
| TOTAL AFTER EXCESS | - | -        |
| GST 7%             | - | -        |
| GRAND TOTAL        | - | -        |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

TRANS EUROKARS PTE LTD

Authorised Signature

4403.72