

ASS. REC. BY:

REF:

CS/EG122009580/Dny³

DE report

ASSIGNMENT

COE Jan 2022

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHC 3061 T Yr Regn: Feb / 2019

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai Ioniq C.C. 1580Colour: Blue A/C: Insured / Std / NI / NASp. Reading: 571958 T/Radio: Insured / Std / NI / NAEng/No: G4LEJU167737C/No: KMHG851CVKU134053

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15R: 11

BS / DUN / EXNOVA / GY / FS / LZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Westlake

Front

Rear

R/Bal. 5 mm R/Bal. 5 mmL/Bal. 5 mm L/Bal. 5 mmD.O.A. 28/09/2022 D.O.I. 29/09/2022Survey held at Hyundai ServiceDes. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Erigo SLB 99M14/2/2023 phany 45 20,500/- in 10 days 2/2(Red, \$ 21812.78, 52%)

Date/Time, File Pass to?

1) 14/3/23

Date/Time, File Return to?

2) _____

☐ : Preli. Report☐ : Final ReportDays Of Repair: 10Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Report Format :

Lump Sum / I.B.I. (\$) _____

Boot Lid Rubber <i>slipped / Hec</i>		1	\$	187.40	\$	187.40
Boot Lid Hinge (LH/RH) <i>HH</i>		2	\$	71.30	\$	142.60
Boot Lid Absorber (LH/RH) <i>HH</i>		2	\$	86.70	\$	173.40
Boot Lid Lock Upper <i>Down</i>		1	\$	224.00	\$	224.00
Boot Lid 'H' Emblem <i>Hec</i>		1	\$	28.00	\$	28.00
Emblem-Hybrid <i>Hec</i>		1	\$	24.30	\$	24.30
Emblem-Ioniq <i>Hec</i>		1	\$	31.30	\$	31.30
Rear Spoiler <i>HH</i>		1	\$	665.40	\$	665.40
Boot Lid Lamp(LH/RH) <i>mostly CRAC 794.40 X2</i>		2	\$	822.00	\$	1,644.00
Boot Lid Trimboard <i>HH</i>		1	\$	259.70	\$	259.70
Boot Lid Trimboard Clips (10pcs) <i>HH</i>		1	\$	11.00	\$	11.00
Boot Lid Glass Upper Moulding <i>HH</i>		1	\$	186.30	\$	186.30
Boot Lid Glass Lower Moulding <i>HH</i>		1	\$	145.20	\$	145.20
Rear Bumper <i>distorted</i>		1	\$	459.40	\$	459.40
Rear Bumper Reinforcement <i>CRAC</i>		1	\$	394.80	\$	394.80
Rear Bumper Reinforcement Bracket (LH/RH) <i>34</i>		2	\$	188.10	\$	376.20
Antenna Assy-SMARTK outer <i>mostly broken</i>		1	\$	689.50	\$	689.50
Rear Bumper Centre Moulding Assy <i>distorted</i>		1	\$	451.25	\$	451.25
Rear Bumper Lower Centre Moulding Assy <i>mostly broken</i>		1	\$	155.00	\$	155.00
Rear Bumper Stay <i>HH</i>		1	\$	138.10	\$	138.10
Rear Bumper Side retainer (LH/RH) <i>src</i>		2	\$	85.80	\$	171.60
Rear Bumper Cover Clips <i>Hec</i>		1	\$	22.00	\$	22.00
Rear Bumper Under Centre <i>CRAC</i>		1	\$	123.85	\$	123.85
Rear Bumper Side Under(LH/RH) <i>src</i>		2	\$	123.10	\$	246.20
Rear Bumper Rear Hook <i>HH</i>		2	\$	94.60	\$	189.20
Rear Bumper Reflector Lamp(LH/RH) <i>HH</i>		2	\$	82.90	\$	165.80
Rear Bumper Reserve Light (Parking Brake Light) <i>socket</i>		1	\$	328.60	\$	328.60
Licence Lamp <i>HH</i> <i>broken</i>		1	\$	193.53	\$	193.53
Tail Lamp(LH/RH) <i>mostly broken 870.40 X2</i>		2	\$	935.40	\$	1,870.80
Rear Panel <i>Double</i>		1	\$	532.00	\$	532.00
Antenna Assy - TRUNK <i>HH</i>		1	\$	689.50	\$	689.50
Rear Panel Garnish <i>defined</i>		1	\$	346.80	\$	346.80
SUB TOTAL					\$	44,201.23
LESS 20%					\$	8,840.25
DISCOUNTED TOTAL					\$	35,360.98
Front Number Plate <i>HH</i>	SN	1	\$	25.00	\$	25.00
Front No Plate Trim Cover <i>HH</i>	SN	1	\$	30.00	\$	30.00
COOLANT <i>HH</i>	SN	1	\$	45.00	\$	45.00
Emblem-Blue Drive (RH) <i>HH</i>	SN	1	\$	26.60	\$	26.60
Reverse camera ASSY <i>HH</i>	SN	1	\$	983.20	\$	983.20
Boot Lid Comfort Logo & Tel No. Sticker <i>Hec</i>	SN	1	\$	35.00	\$	35.00
Boot Lid Comfort Cablink Tel No. Sticker <i>HF</i>	SN	1	\$	30.00	\$	30.00
Rear No.Plates + Trim Cover <i>CRAC/Down</i>	SN	1	\$	45.00	\$	45.00
Rear Windscreen Sealant <i>Hec</i>	SN	2	\$	46.00	\$	92.00
Rear Bumper Rubber Mat <i>Hec</i>	SN	1	\$	50.00	\$	50.00
Rear Bumper Reverse Sensor <i>Down</i>	SN	1	\$	180.00	\$	180.00
SUB TOTAL					\$	1,541.80
Labour Charge						
Panel Beating		1	\$	2,200.00	\$	2,200.00

1588.80

7704.20

1740.80

28,646.20

22,956.96

402.00

900/-

Spray Painting Charge	1	\$1,800.00	\$1,800.00
Wiring Charge	1	\$100.00	\$100.00
Tuff Kote	1	\$100.00	\$100.00
Towing Charge	1	\$80.00	\$80.00
Remove/Refix Rear Windscreen Glass	2	\$120.00	\$240.00
Remove/Refix Reverse Sensor	1	\$120.00	\$120.00
Remove/Refix Radiator	1	\$90.00	\$90.00
Remove/Refix Aircon & Refill Gas	1	\$130.00	\$130.00
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00
TOTAL LABOUR			\$5,410.00
ESTIMATE TOTAL			\$42,312.78

900/-
30/-
40/-
40/-
80/-
40/-
50/-
80/-
150/-

2270.00

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company. Please send your book value request to: claims_ltr@bifrostauto.com

29/09/2022 e 1700m

Not Andu

L/srue

10 days.

LKK Andu

25,628.96

4/s 20,500/-

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	821R
Vehicle Details	
Vehicle No.:	SHC3061T
Vehicle to be Exported:	Yes
Intended Deregistration Date:	30 Sep 2022
Vehicle Make:	HYUNDAI
Vehicle Model:	AE IONIQ HEV 1.6 DCT
Primary Colour:	Blue
Manufacturing Year:	2018
Engine No.:	G4LEJU167737
Chassis No.:	KMHC851CVKU134053
Maximum Power Output:	103.6 kW (138 bhp)
Open Market Value:	\$25,131.00
Original Registration Date:	01 Feb 2019
First Registration Date:	01 Feb 2019
Transfer Count:	0
Actual ARF Paid:	\$12,184.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	31 Jan 2027
PARF Rebate Amount:	\$9,138.00
Intended COE Rebate Details	
COE Expiry Date:	31 Jan 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$20,582.00
COE Rebate Amount:	\$11,148.00
Total Rebate Amount:	\$20,286.00
Message	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 28 Sep 2022

OK