

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

*Lee / Admin*

SJ LEASING PTE LTD  
 60 JALAN LAM HUAT #05-11 CARROS  
 CENTRE  
 SINGAPORE 737869

## TAX INVOICE

*7P Budget Direct.  
 Venm.*

Repair Code : CLM17395

Date in : 21/08/2022

Vehicle Num. : SLM8969S

Model : MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT

Chassis/Eng# : JM6BN22A8H0148658/P520438709

Contact : 97711118, 81338703

### Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Del'd</i>	1	1031.00	<input checked="" type="checkbox"/> 1,031.00
FRONT BUMPER LH LAMP <i>3 new</i>	1	155.00	<input checked="" type="checkbox"/> 155.00
FRONT BUMPER LH LAMP COVER <i>3 new</i>	1	72.00	<input checked="" type="checkbox"/> 72.00
FRONT BUMPER SIDE RETAINER L/R <i>LH 2nd</i>	2	18.90	<i>18.90</i> <input checked="" type="checkbox"/> 37.80
FRONT LH FENDER <i>Del'd</i>	1	350.00	<i>3691.90</i> <input checked="" type="checkbox"/> 350.00
FRONT LH FENDER INNER SHIELD <i>torn</i>	1	145.00	<input checked="" type="checkbox"/> 145.00
FRONT LH HEADLAMP <i>Del'd</i>	1	1070.00	<i>2953.52</i> <input checked="" type="checkbox"/> 1,070.00
FRONT LH KNUCKLE ARM <i>New</i>	1	405.00	<input checked="" type="checkbox"/> 405.00
FRONT LH KNUCKLE ARM BEARING <i>2nd</i>	1	568.00	<input checked="" type="checkbox"/> 568.00
FRONT LH LINKAGE <i>New</i>	1	64.70	<input checked="" type="checkbox"/> 64.70
FRONT LH LOWER ARM <i>Best</i>	1	509.00	<input checked="" type="checkbox"/> 509.00
FRONT LH SHOCK ABSORBER <i>New</i>	1	360.00	<input checked="" type="checkbox"/> 360.00
FRONT LH SHOCK ABSORBER MOUNTING <i>New</i>	1	91.00	<input checked="" type="checkbox"/> 91.00
FRONT LH SPORT RIM <i>Del'd</i>	1	1162.00	<i>650 (SW)</i> <input checked="" type="checkbox"/> 1,162.00
Subtotal before discount			6,020.50
Percentage discount 20%			1,204.10
<b>Sub-total 1</b>			<b>4,816.40</b>
FRONT BUMPER CLIPS - SET <i>New</i>	1	50.00	<i>30</i> <input checked="" type="checkbox"/> 50.00

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 T1 No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

**SJ LEASING PTE LTD**  
 60 JALAN LAM HUAT #05-11 CARROS  
 CENTRE  
 SINGAPORE 737869

Contact : 97711118, 81338703

**TAX INVOICE**

Repair Code : CLM17395  
 Date in : 21/08/2022  
 Vehicle Num. : SLM8969S  
 Model : MAZDA3 4-DOOR SEDAN 1.5L SP.6EAT  
 Chassis/Eng# : JM6BN22A8H0148658/P520438709

FRONT LH FENDER INNER SHIELD CLIPS - SET <i>New</i>	1	50.00	<i>30</i>	<del>50.00</del>
FRONT LH TYRE <i>New</i>	1	380.00	<i>60</i>	<del>380.00</del>
Subtotal before discount				480.00
Percentage discount 0%				0.00
<b>Sub-total 2</b>				480.00
<b>Parts-total</b>				<b>5,296.40</b>

**LABOUR**

- To remove, reinstall electrical wiring harness, check lighting. (to FR)
- To remove, reinstall front suspension undercarriage parts. (to FR)
- To road test driving, check and resetting wheel alignments system.
- To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.
- To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.
- To apply anti-rust chemical on repaired and replaced panel.

<b>Labour Total</b>	<b>1,630.00</b>
<b>Parts &amp; Labour Total</b>	<b>6,926.40</b>

*1200*

<i>30</i>	<del>60.00</del>
<i>150</i>	<del>220.00</del>
<i>80</i>	<del>100.00</del>
<i>400</i>	<del>600.00</del>
<i>500</i>	<del>600.00</del>
<i>40</i>	<del>50.00</del>

*Adrian Lj*  
*H/S.*

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

*total: 4863.52*  
*C/S: 3.9k.*  
*05 Days.*  
*3.9k.*