

MHL Automobile Service

SLB8927X Toyota Altis

Accident along

S/N	Qty	Description	(S\$)	Condition
<u>Parts</u>				
1	1pcs	Rear bumper	\$ 794.00	620 Lut
2	2pcs	Rear bumper reflector	\$ 54.20	X NN
3	1pcs	Rear bumper sensor	\$ 195.00	X NN
4	1pcs	Rear bumper side retainer	\$ 130.00	X NN
5	1pcs	Rear bumper sponge	\$ 121.30	X NN
6	1pcs	Rear bumper re enforcement	\$ 235.20	R dent
7	1pcs	Boot lid logo	\$ 89.70	X
8	2pcs	Boot lid emblem "altis"	\$ 75.70	X
9	1pcs	Boot lid emblem "corolla"	\$ 80.30	X
10	1pcs	Boot lid rh reflector	\$ 288.70	X NN
11	1pcs	Rh taillamp	\$ 380.10	X
12	1pcs	Rear muffler	\$ 1,237.39	X

Total \$ 3,681.59
List -25% \$ 920.40
Parts Sub Total \$ 2,761.19

Special Nett

13	1sets	Rear bumper clips	\$ 50.00	MEC
14	1sets	Rear rh fender inner trim clips	\$ 50.00	X
Total			\$ 100.00	

<u>Labour</u>				
1		To check wiring sytsem.	\$ 100.00	30
2		To transfer rear bumper sensor attactment.	\$ 100.00	30
3		To R&R rear inner trim for hot work repair.	\$ 200.00	X
4		To carry out body cavity preservation.	\$ 200.00	X
5		To reset and reprogramme after repair the vehicle .	\$ 200.00	X
6		To r&r rear muffler.	\$ 100.00	X
7		Labour charges	\$ 800.00	400

8	Spray painting	\$	1,000.00	400
	Labour Total:	\$	2,700.00	800
	Sub Total (labour and parts):	\$	5,561.19	1473

Vehicle is at Blk 3006 Ubi Road 1 #01-360 Singapore 408700

Please arrange your surveyor to come down to survey the vehicle.

20% = 294

Final 1180
✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

17/11/22
L/S 2 days