

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933
Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chan Kian Chuan

Date: 20 Dec 2022

Preliminary Advice

Insured Vehicle No	: EY10E		
TP Vehicle No	: SMR4877L	Accident Date	: 23/09/2022
Make	: MERCEDES-BENZ C180	Assignment Date	: 28/09/2022
Date of Inspection	: 29/09/2022	Est. Duration of Repair	: 5
Inspection At	: TWINCAR AUTOMOTIVE PTE LTD (KAKI BUKIT) BLK 2 KAKI BUKIT, #01-17/18 KAKI BUKIT AUTOHUB SINGAPORE 417921		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	20,699.10
Revised Amount	:S\$	14,476.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	14,476.00
Lump Sum Repair	:S\$	11,500.00

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.