

TwinCar AUTOMOTIVE PTE LTD

Lark Admin

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

GOH CHUA SENG
BLK 607 SENJA ROAD #19-12
SINGAPORE 670607

Contact : 98577753

TAX INVOICE

TP Allianz.

Xiao Chen.

Repair Code : CLM15668

Date in : 24/09/2022

Vehicle Num. : SMR4877L

Model : MERCEDES BENZ C180 AVANTGARDE (R17 LED)

Chassis/Eng# : WDD2050402R026397/27491030287981

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Repair</i>	1	1698.00	1,698.00
FRONT BUMPER RH INNER SIDE BRACKET <i>new</i>	1	115.00	115.00
FRONT BUMPER RIVET <i>new</i>	15	9.00	135.00
FRONT BUMPER SIDE RETAINER L/R <i>new</i>	2	24.00	48.00
FRONT RH HEADLAMP <i>Amber</i>	1	3580.00	3580.00
FRONT RH KNUCKLE ARM <i>new</i>	1	1370.00	1370.00
FRONT RH KNUCKLE ARM BEARING <i>new</i>	1	598.00	598.00
FRONT RH LINKAGE <i>new</i>	1	105.00	105.00
FRONT RH LOWER ARM <i>Best</i>	1	685.00	685.00
FRONT RH LOWER ARM STARY ARM <i>Best</i>	1	674.00	674.00
FRONT RH SHOCK ABSORBER <i>Best</i>	1	805.00	805.00
FRONT RH SHOCK ABSORBER MOUNTING <i>new</i>	1	295.00	295.00
FRONT RH SHOCK ABSORBER RUBBER <i>new</i>	1	36.00	36.00
FRONT RH SHOCK ABSORBER SPONGE <i>new</i>	1	92.00	92.00
FRONT RH SPORT RIM <i>at</i>	1	650.00	650.00
FRONT RH UPPER ARM <i>new</i>	1	898.00	898.00
STEERING RACK & PINION ASSY <i>Best</i>	1	8015.00	8015.00

14340

12906

(7644.88)

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

GOH CHUA SENG
BLK 607 SENJA ROAD #19-12
SINGAPORE 670607

Contact : 98577753

TAX INVOICE

Repair Code : CLM15668
Date in : 24/09/2022
Vehicle Num. : SMR4877L
Model : MERCEDES BENZ C180 AVANTGARDE (R17 LED)
Chassis/Eng# : WDD2050402R026397/27491030287981

Subtotal before discount		19,799.00
Percentage discount 10%		1,979.90
Sub-total 1		17,819.10
FRONT BUMPER CLIPS - SET <i>me</i>	1	50.00 <i>32</i> 50.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00 <i>x</i> 50.00
FRONT RH TYRE <i>torn</i>	1	550.00 <i>300</i> 550.00
Subtotal before discount		650.00
Percentage discount 0%		0.00
Sub-total 2		650.00
Parts-total		18,469.10

LABOUR

To reset system after repair works

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

Labour Total 2,230.00
Parts & Labour Total 20,699.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplemental survey can be resurveyed and is subject to final approval from Insurance Company

This is a computer-generated document which requires no signature.

Acknowledged by Repairer

page 2

total: 14476
L/S. 11.5K.
0.5 Days.
11.5K