



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
 T 65 6758 2222 F 65 6257 6931
 E sales@scauto.com.sg
 scauto.com.sg

Co. Reg. No. 199800107D

M/S CHUAN LIM CONSTRUCTION PTE LTD
 20 SENOKO DR

SINGAPORE 758207

Insured CHUAN LIM CONSTRUCTION PTE LTD

Policy CV1/GA352771/1

Damaged Vehicle No: XD9160G

Final Bill

GST Reg. No: 19-9800107D

Date: 4/11/2022

Our Case Ref. SC22/09/142/4CL-TP

Accident Date 24/9/2022

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	FRONT DOOR LH	1 PC	\$3,880.60	10.00%	\$3,492.54
2	SIDE STEP PANEL LH	1 PC	\$922.00	10.00%	\$829.80
3	SIDE STEP LOWER LH	1 PC	\$568.50	10.00%	\$511.65
4	SIDE STEP COVER LH	1 PC	\$765.00	10.00%	\$688.50
5	SIDE STEP PANEL CAP LH	1 PC	\$360.20	10.00%	\$324.18
6	FRONT BUMPER LOWER ASSY	1 PC	\$1,880.60	10.00%	\$1,692.54
7	FRONT BUMPER INNER BRACKET LH	1 PC	\$630.00	10.00%	\$567.00
8	FRONT HEADLIGHT HOUSING LH	1 PC	\$1,255.00	10.00%	\$1,129.50
9	FRONT SIDE BUMPER LOWER LH	1 PC	\$1,095.00	10.00%	\$985.50
10	FRONT HEADLIGHT BRACKET LH	1 PC	\$1,150.00	10.00%	\$1,035.00
11	FRONT HEADLIGHT INNER BRACKET LH	1 PC	\$715.00	10.00%	\$643.50
12	FOG LAMP BRACKET LH	1 PC	\$312.60	10.00%	\$281.34
13	FOG LAMP INNER BRACKET LH	1 PC	\$325.00	10.00%	\$292.50
14	FRONT HEADLIGHT SIGNAL LAMP LH	1 PC	\$315.00	10.00%	\$283.50
15	FRONT BUMPER VENT LH	1 PC	\$788.00	10.00%	\$709.20
16	BODY STICKER	1 PC	\$80.00	-	\$80.00
17	SUNDRIES	1 PC	\$50.00	-	\$50.00



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133

T 65 6758 2222

F 65 6257 6931

E sales@scauto.com.sg

scauto.com.sg

Co. Reg. No. 199800107D

M/S CHUAN LIM CONSTRUCTION PTE LTD

20 SENOKO DR

SINGAPORE 758207

Insured CHUAN LIM CONSTRUCTION PTE LTD

Policy CV1/GA352771/1

Damaged Vehicle No: XD9160G

Final Bill

GST Reg. No: 19-9800107D

Date: 4/11/2022

Our Case Ref. SC22/09/142/4CL-TP

Accident Date 24/9/2022

S/no	Description	QTY	Price	Disc	Amount
<u>Labour Charges</u>					
1	LABOUR TO REMOVE, REINSTALL AND CHECK FRONT BUMPER WIRE HARNESS.	1	\$200.00	-	\$200.00
2	LABOUR TO REMOVE, REPAIR AND REINSTALL FRT BUMPER, FRONT DOOR LH, FRT PANEL INNER LH, FRT BUMPER SUPPORT.	1	\$2,560.00	-	\$2,560.00
3	LABOUR TO REMOVE AND REINSTALL BODY STICKER	1	\$50.00	-	\$50.00
4	LABOUR TO RESPRAY FRONT DOOR LH, FRT BUMPER.	1	\$640.00	-	\$640.00
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK	1	\$80.00	-	\$80.00
Sub Total					\$ 17,126.25
Lump Sum					\$ 13,700.00
GST (7%)					\$ 959.00
Total Amount					\$ 14,659.00

Authorised Signature