



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Not Authorized
11 Rm @ 13,700/-
Return After Rain

Co. Reg. No.

199800107D

5 days

M/S	ALLIANZ INSURANCE SINGAPORE PTE LTD
	79 ROBINSON RD, #09-01
	SINGAPORE 068897
Insured	CHUAN LIM CONSTRUCTION PTE LTD
Policy	5125529432-000051

ESTIMATE BILL

GST Reg. No: 199800107D

Date: 30/9/2022

Our Case Ref.

Accident Date 24/9/2022

Damaged Vehicle No: XD9160G

S/no	Description	QTY	Price	Amount	Remark
Replaced Parts					
1	FRONT DOOR LH	Ry 1 PC	\$3,880.60	\$ 3,880.60	✓
2	SIDE STEP PANEL LH	CM 1 PC	\$ 922.00	\$ 922.00	✓
3	SIDE STEP UPPER LH	1 PC	\$ 566.00	\$ 566.00	x
4	SIDE STEP LOWER LH	1 PC	\$ 568.50	\$ 568.50	✓
5	SIDE STEP COVER LH	CM 1 PC	\$ 765.00	\$ 765.00	✓
6	SIDE STEP PANEL CAP LH	CM 1 PC	\$ 360.20	\$ 360.20	✓
7	FRONT BUMPER LOWER ASSEMBLY	BHID 1 PC	\$1,880.60	\$ 1,880.60	✓
8	FRONT BUMPER VENT LH	CM 1 PC	\$ 788.00	\$ 788.00	✓
9	FRONT BUMPER INNER BRACKET	CM 1 PC	\$ 630.00	\$ 630.00	✓
10	FRONT HEADLIGHT HOUSING LH	CM 1 PC	\$1,255.00	\$ 1,255.00	✓
11	FRONT SIDE BUMPER LOWER LH	Ry 1 PC	\$1,095.00	\$ 1,095.00	✓
12	FRONT HEADLIGHT BRACKET LH	CM 1 PC	\$1,150.00	\$ 1,150.00	✓
13	FRONT HEADLIGHT INNER BRACKET LH	CM 1 PC	\$ 715.00	\$ 715.00	✓
14	FRONT HEADLIGHT LH	Sn 1 SET	\$1,690.00	\$ 1,690.00	x
15	FOG LAMP BRACKET LH	CM 1 PC	\$ 312.60	\$ 312.60	✓
16	FOG LAMP INNER BRACKET LH	CM 1 PC	\$ 325.00	\$ 325.00	✓
17	FOG LAMP LH	1 PC	\$ 520.00	\$ 520.00	x
18	FRONT FENDER LINER (BACK) LH	Sn 1 PC	\$ 968.00	\$ 968.00	x
19	FRONT HEADLIGHT SIGNAL LAMP LH	Bu 1 PC	\$ 315.00	\$ 315.00	✓
20	BODY STICKER	M 1	\$ 350.00	\$ 350.00	✓
21	SUNDRIES		\$ 200.00	\$ 200.00	✓
Labour Charges					
1	LABOUR TO REMOVE, REINSTALL AND CHECK FRONT BUMPER WIRELESS		\$ 350.00	\$ 350.00	2001
2	LABOUR TO REMOVE, REPAIR AND REINSTALL FRT BUMPER, FRT DOOR L FRT PANEL INNER LH, FRT BUMPER SUPPORT.		\$ 5,000.00	\$ 5,000.00	25601
3	LABOUR TO REMOVE AND REINSTALL BODY STICKER		\$ 250.00	\$ 1,920.00	x
4	LABOUR TO RESPRAY FRT DOOR LH, FRT BUMPER ASSY		\$ 1,920.00	\$ 1,920.00	6401
5	LABOUR TO CARRY OUT DIAGNOSTIC CHECK		\$ 250.00	\$ 250.00	801
TOTAL				\$ 35,096.50	

LKK Auto Consultants hence notify

the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and

Not acknowledged by Repairer

Signature:

Date: