

SA INFINITE PAINTWORKS PTE LTD

Endless Possibilities
By SA Group
Co Reg No. 202039049Z

24th August 2022

Our Ref: SMX4056H
Your Ref: SMV9278L

India International Insurance Pte Ltd
Motor Claims Department
64 Cecil Street
#04-05 IOB Building
Singapore 049711

Dear Sirs/Madam,

ACCIDENT INVOLVING SMX4056H AND SMV9278L ALONG TELOK BLANGAH RD ON 19.03.2022.

We are the representative for Muhammad Faqihuddin Bin Mohamad Mahriz, whose vehicle registration number **SMX4056H** was damaged in the above accident.

We are instructed to claim for damages against your insured in connection with the above-captioned road traffic accident driven by your insured.

We are instructed that the accident was caused by your insured's negligence and/or management of motor vehicle registration **SMV9278L**. As a result of the accident, our client's vehicle was damaged and our client had been put to loss and expense, particulars of which are as follows:-

Cost of repairs	\$	4,000.00
Loss of use for 06 days @ \$120/day	\$	720.00
Survey report	\$	504.00
LTA search fee	\$	7.45
	\$	<u>5,231.45</u>

Enclosed are the supporting documents for your perusal :-

GIA

Repair bill

Kindly let us have your payment of **\$ 5,231.45** in our workshop's name within the next 14 days.

Please do not hesitate to contact our Ms Irene at 63851171 or email motor@iaconsultingsg.com should you have any queries on your matter. We thank you for your kind attention and appreciate your quick remittance.

Yours faithfully,



Encl.

LETTER OF AUTHORITY

Muhammad Faqihuddin
We/I, Bin Mohamad Mahriz ("the third party claimant") of UEN/NRIC No. S9441443A, owner of vehicle Reg.No SMX 4056H hereby authorize M/s SA Infinite Paintworks Pte Ltd ("the workshop") to act for me with respect to my claim for repair costs and/or rental and/or loss of use and/or survey fee ("claim") for my vehicle no. SMX 4056H that was damaged pursuant to the accident which occurred on 19.3.2022 along Telok Blangah Rd involving vehicle no/s SMV 9278L ("the accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this

of

20



Signed by the third party claimant

> Back to OneMotoring



Land Transport Authority
10 Sin Ming Drive
Singapore 575701
GST Registration No. : M4-0006529-2

Print Date/Time : 28 Mar 2022 / 18:17:29

Receipt Date/Time : 28 Mar 2022 / 18:17:29

Tax Invoice/Receipt

Receipt No. : ITNET-00000-220328-003842

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
	Result of Insurance Enquiry - SMV9278L As at 19 Mar 2022/12:35:00 Insurance Co: INDIA INT'L INS PTE LTD			
1	Insurance Enquiry - SMV9278L Enquiry Fee 20220328181609170790	7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	Total Before Rounding	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
	Paid By			
	421808XXXXXX3088	eNETS Credit Card		7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

SA INFINITE
PAINTWORKS PTE LTD

Endless Possibilities
By SA Group
Co Reg No. 202039049Z

Customer Name:
Muhammad Faqihuddin
Bin Mohamad Mahriz

INVOICE No : 202160
Date Enter : 31/05/2022
Date Collect :
A/C Code :
Job No :
Veh Reg No : SMX4056H
Mileage :

Description/s	Quantity	Unit Price SGD \$	Amount SGD \$
---------------	----------	-------------------	---------------

Car Model: Mercedes A200

- Cost of Repairs	4,000.00	4,000.00
Total Amount		4,000.00
Add GST 7%		0.00
Deposit Amount		0.00
Grand Total		<u>4,000.00</u>

SINGAPORE DOLLAR:
Four Thousand Only

For SA Infinite Paintworks Pte Ltd

Confirm & Accepted By



Authorised Signature

Customer Signature

Office Address: 25 Kaki Bukit Road 4 #06-43 Synergy@ KB Singapore 417800
Email: info@infinitepaintworks.com / admin@infinitepaintworks.com

Our reference: 22 - 170716

Date: 31/05/2022

INVOICE NO. 170716**Muhammad Faqihuddin Bin Mohamad Mahriz**
c/o SA Infinite Paintworks Pte Ltd
25 Kaki Bukit Rd 4
#06-43 Synergy @ KB
Singapore 417800Registration No. **SMX4056H**

We enclose our fee note for your kind attention, which remains payable irrespective of the outcome of this case.

S/No.	Description of Services Provided	Qty	Amount
1	Being vehicle damage assessment report, inspection, photographs, transport and miscellaneous.	1	\$ 504.00
Total amount			<u><u>\$ 504.00</u></u>

Please kindly cross all cheques made payable to "Impact Analysis Consultant".

We thank you in anticipation for your prompt payment.

L. L. Tan (Ms)
Principal Consultant

Our reference: 22 - 170716

Date: 31/05/2022

c/o SA Infinite Paintworks Pte Ltd
25 Kaki Bukit Rd 4
#06-43 Synergy @ KB
Singapore 417800

Dear Sirs

RE: Road Traffic Accident on 19/03/2022
Muhammad Faqihuddin Bin Mohamad Mahriz

In accordance with your instructions received in this office on 04/04/2022, we made arrangements to examine the vehicle on 04/04/2022 at above-mentioned address. The following data was recorded:


Vehicle details

Make	Mercedes Benz	Registration	SMX4056H
Model	A200 FL Style	Chassis	WDD1760432J507561
Colour	White	Gearbox	Auto
Odometer	71580km	Paintwork	Fair
Steering	In order	Brakes	In order
Condition	Fair		

Tyre Depths

Front left	225/40ZR18	85% Falken
Front right	225/40ZR18	85% Falken
Rear left	225/40ZR18	85% Falken
Rear right	225/40ZR18	85% Falken

Impact Direction & Area of Damage:



Status	REPAIRABLE
Magnitude	Medium
Legal status	Unroadworthy

Following our examination of the accident damage, we have calculated repair times and method, which are detailed on page 2 & 3. We would recommend a sum of \$4,000.00 and 4 working days for repair, which is sufficiently lower than the pre accident value to render the vehicle an economically and physically reliable proposition.

Our reference 22 - 170716
Date 31/05/2022
Page 2

Section A: Damaged Parts Assessment

Part's Description	Qty	Condition As inspected	Repairer's Estimate	Our Adjustment
List Items:				
Tail gate emblem " A200"	1	necessary	65.00	65.00
Tail gate emblem "logo"	1	necessary	85.00	85.00
Tail gate emblem "C&C"	1	necessary	45.00	45.00
Rear bumper	1	deformed	1638.00	1638.00
Rear bumper center bracket	1	deformed	105.00	105.00
Rear bumper reinforcement	1	bent	655.00	655.00
Rear bumper lower lid	1	deformed.torn	438.30	438.30
Rear bumper lip inner bracket	1	fractured.deformed	109.00	109.00
Rear bumper reverse sensor @\$234.20	4	2pcs malfunction	936.80	468.40
Rear end panel top garnish	1	holder broken	204.80	204.80
Sub- Total costs			4281.90	3813.50
Percentage discount : 10%			428.19	381.35
Sub-Total costs for parts			3853.71	3432.15

Special Nett Items:

Rear bumper clips	set	necessary	50.00	50.00
Sub-Total costs for parts			50.00	50.00

Parts Repair

Tail gate - dented/misaligned	1	repair.respray	0.00	0.00
Rear end panel - dented	1	repair.respray	0.00	0.00
Sub- Total costs			0.00	0.00
Total costs for parts			3903.71	3482.15

Our reference 22 - 170716

Date 31/05/2022

Page 3

Section B: Labour Cost Calculation

	Hourly rate	Manhr. Req.	Total
To dismantle, replace, cut, weld, knock out dents to straighten accident parts as-mentioned on the 'Parts Repair' column inclusive of replacement parts.	\$ 45.00	12	\$ 540.00
Putty & Spray painting to adjacent panels. Job allowance. Paint / material.	Sub-contract work.		\$ 700.00
Apply rust proofing on the adjacent panels.	Sub-contract work.		\$ 30.00
Remove and replace rear bumper reverse sensor & conduct distance safety setting.	\$ 45.00	1.7	\$ 76.50
Specialist charges - Diagnostic fault code / reset	-	-	\$ 150.00
Wiring / bulb checking (inclusive of re-focus / re-adjust on angle of light intensity.)	\$ 45.00	0.6	\$ 27.00
Total labour cost			\$ 1,523.50

Manhour rate and the number of manhours required for each repairing task are formulated based on individual workshop's operating cost and in-house@ IA Research Guidelines respectively.

Our reference 22 - 170716

Date 31/05/2022

Section C: Summary Table of Total Repair Cost

Description		Cost
Damaged Parts Assessment (See section A)		\$3,482.15
Labour Cost Calculation (See section B)		\$1,523.50
Total Cost		\$5,005.65
Lump Sum		\$1,001.13
Further discount	20%	
Total Repair Cost		\$4,000.00

We would recommend a sum of \$4,000.00 and 4 working days for repair.
No further items will be approved without our expressed written agreement. Any significant additional items will be subject to a supplementary report.

Mechanical Engineer, Accident Expert Witness, Licensed Appraiser (Automobile)
B.Eng. (Hons, NUS)
Diploma.Mechanical Engineering
NTC-2 Automovite Technology
Sr.MIES, Institution of Engineers, Singapore (#20100091)
MATAI, Maryland Association of Traffic Accident Investigators
IAARS, International Association of Accident Reconstruction Specialists
PMC of Singapore Business Advisors & Consultants Council
ACTA certified Trainer, Singapore
Enterprise Singapore - Recognised Certification for Management Consultants
IMI Professional Certificate In Vehicle Accident Damage Assessment (UK)

Subsidiaries of Impact Analysis:

• Impact Analysis Consultant • IABN Pte Ltd • Impact Analysis Solution Pte Ltd
www.iaconsultingsg.com

