

**Success United Pte Ltd** (Co.Reg.No:200402570G)

2 Kaki Bukit Ave 2 #01-33, Kaki Bukit AutoHub

Singapore 417921

Tel: 6746 1515 Fax: 6748 5015 Email: sirina@successunited.com.sg

INSURER: **Allianz Insurance Singapore Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	SU220111
Policy No:	SP2002159546-01	Date of Loss:	23/09/2022
Vehicle Reg. No.:	SNE818R	Driveable?	
Driver Age/Info:	42	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	LEE TECK SOON ERIC	Contact No:	+6588336669
Driver:	LEE TECK SOON ERIC		
Make/Model:	BMW 740LI, 3.0 (A)	Vehicle Reg. Date:	01/03/2016
Vehicle Colour:	WHITE		
Engine No:	23329419B58B30A	Chassis No:	WBA7E22090G522977
Odometer:	105142 KM		
Paint Type:			
Total Loss?	<b>NO</b>		
Est. Duration of Repair (day)	5		
Present Location:	SUCCESS UNITED PTE LTD (HQ)		

**COST OF CLAIMS**

	<b>Amount</b>
Parts	23,704.10
Miscellaneous Items	0.00
Labour	1,050.00
Paintwork Labour	800.00
Towing	0.00
	<b>Gross Total (S\$) 25,554.10</b>
	<b>+ GST 7.00% (S\$) 1,788.79</b>
	<b>Nett Amount (S\$) 27,342.89</b>

**This claim is handled by: LAW YI TING**

Generated using Merimen e-Claims Internet Estimation &amp; Adjusting System

## REPAIR DETAILS

### Reference

**Part Source:** MRM-SG      Version: 1.0 (Last Synchronised: 28 Sep 2022)  
**Parts:** 143      BMW 740LI 3.0 (A) (Catalogue:Merimen Singapore 1.0)  
**Labour:** Repairer's      (Price-denominated Standard List)  
**Print Code:** Success United Pte Ltd/SNE818R/28/09/2022 17:48  
**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page  
**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk \*.

### Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*Front Bonnet <i>Rev</i>	0.00	0.00	*3,500.00 F	✓
2	1		*Front Bumper Assy <i>Del</i>	0.00	0.00	*2,100.00 F	✓
3	1		*Front Bumper Inner Base Frame ? nn	0.00	0.00	*320.00 F	✗
4	2		*Front Bumper Side Holder (LH/RH) <i>Me n</i>	0.00	0.00	*180.00 F	✗
5	2		*Front Bumper Bracket (LH/RH) ? nn	0.00	0.00	*130.00 F	✗
6	1		*Front Bumper Inner Sponge ? deformed	0.00	0.00	*110.00 F	✓
7	1		*Front Bumper No.Plake Garnish <i>Del</i>	0.00	0.00	*90.00 F	✓
8	1		*Front PDC Sensor (Packing Distance Sensor) ? nn	0.00	0.00	*395.00 F	✗
9	1		*Front Bumper Lower Air Grille (Center) <i>amb</i>	0.00	0.00	*150.00 F	✓
10	1		*Front Bumper Inner Lower Bracket ? nn	0.00	0.00	*450.00 F	✗
11	2		*Front Grille Assy (LH/RH) <i>amb</i>	0.00	0.00	*460.00 F	✓
12	1		*Front Bumper Reinforcement ? nn	0.00	0.00	*850.00 F	✗
13	2		*Front Headlamp Assy (LH/RH)	0.00	0.00	*11,940.00 F	✗
14	2		*Front Headlamp Bracket (LH/RH) <i>Me n</i>	0.00	0.00	*156.00 F	✗
15	1		*Front Grille Inner Motor ? nn	0.00	0.00	*220.00 F	✗
16	1		*Front Grille Inner Vent ? nn	0.00	0.00	*430.00 F	✗
17	1		*Front Bumper Clips <i>Me</i>	0	0.00	*30.00 FS	✓
18	1		*Front No.Plake with Frame <i>amb</i>	0	0.00	130 *45.00 FS	✓

F=Franchise part. S=SpcNett.

Sub Total (S\$)	21,556.00
+ Margin on L,N Items 10.00% (S\$)	2,148.10
Total Parts (S\$)	23,704.10

Success United Pte Ltd/SNE818R/28/09/2022 17:48. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

# Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

## Estimates on Labour

No	Particulars	Lab.Type	Amount
<b>Paintwork Labour</b>			
1	To putty & respray painting on bonnet, bumper, support panel	New	<del>800.00</del> 500
<b>Labour Items</b>			
2	To remove, repair & replaced damaged body parts, realign bodywork, & where consistent to the accident	New	<del>900.00</del> 450
3	To remove, rearrange electrical wirings, check lightings	New	<del>150.00</del> 30
Gross Labour Cost (S\$)			1,850.00

Success United Pte Ltd/SNE818R/28/09/2022 17:48. Not valid without Reference section.  
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian Lj  
30/09/22  
04 Days  
P/P.