



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705		Ref: CS/SMR22009598/Avy3m4 Date: 23/12/2022 Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 5332D	Veh. Inspected	SNB 6140M
Policy No.		Coverage (\$)	0.00
Claim No.	TAX/09/22/2075	Excess (\$)	0.00
Assign From	HUA YEN	Assign Date	29/09/2022
2. Vehicle Particulars & Condition			
Make & Model	MINI COOPER COUNTRYMAN	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2011
Chassis No.	WMWZC32010WM94554	Colour	WHITE
Odometer	159747 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	GOODYEAR	6 mm
L/H Front Tyre	215/55 R17	GOODYEAR	6 mm
R/H Rear Tyre	215/55 R17	GOODYEAR	6 mm
L/H Rear Tyre	215/55 R17	GOODYEAR	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	28/09/2022	Inspection Date	29/09/2022
Survey held at	TWINCAR AUTOMOTIVE PTE LTD 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	