

TwinCar AUTOMOTIVE PTE LTD

Kal. Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

PIERCE SIM WEI ZHI
BLK 22 CHOA CHU KANG GROVE #07-53
SINGAPORE 688213

Contact : 98713154, 81837891

TAX INVOICE

Repair Code : CLM15675

Date in : 28/09/2022

Vehicle Num. : SNB6140M

Model : MINI COOPER S COUNTRYMAN 1.6 AT HID TC FWD

Chassis/Eng# : WMWZC32010WM94554/A194J069N18B16A

T P SMRT.
Veran.

Parts and Labour Assessment

| Description of part | Qty | Unit Price | 1055 Amount |
|--|-----|------------|----------------------------|
| FRONT BONNET <i>Dented</i> | 1 | 1546.50 | ✓ 1,546.50 |
| FRONT BONNET 'LOGO' EMBLEM <i>new</i> | 1 | 71.80 | ✓ 71.80 |
| FRONT BONNET RUBBER GUIDE STOPPER L/R <i>new new</i> | 2 | 35.00 | X 70.00 |
| FRONT BUMPER (LOWER) <i>lit</i> | 1 | 253.95 | ✓ 253.95 |
| FRONT BUMPER (TOP) <i>Distorted</i> | 1 | 810.70 | ✓ 810.70 |
| FRONT BUMPER INNER UPPER FRAME BRACKET <i>Dented</i> | 1 | 57.95 | ✓ 57.95 |
| FRONT BUMPER LH FOGLAMP <i>cracked.</i> | 1 | 318.30 | ✓ 318.30 |
| FRONT BUMPER LOWER REINFORCEMENT <i>Best</i> | 1 | 221.00 | ✓ 221.00 |
| FRONT BUMPER LOWER SPONGE <i>cracked.</i> | 1 | 63.05 | 580 ✓ 63.05 |
| FRONT BUMPER REINFORCEMENT <i>Dented</i> | 1 | 799.40 | ✓ 799.40 |
| FRONT LH FENDER <i>Dented</i> | 1 | 476.95 | ✓ 476.95 |
| FRONT LH FENDER ARCH GARNISH <i>Missing</i> | 1 | 171.15 | ✓ 171.15 |
| FRONT LH FENDER INNER SHIELD <i>new new</i> | 1 | 134.60 | X 134.60 |
| FRONT LH FENDER LAMP <i>new</i> | 1 | 75.35 | X 75.35 |
| FRONT LH FENDER LAMP GARNISH <i>new</i> | 1 | 129.95 | X 129.95 |
| FRONT LH HEADLAMP <i>cracked</i> | 1 | 1857.35 | 1420 ✓ 1,857.35 |
| FRONT LH HEADLAMP CHROME MOULDING <i>Missing</i> | 1 | 180.05 | ✓ 180.05 |
| FRONT LH HEADLAMP CONTROL UNIT <i>new</i> | 1 | 673.50 | X 673.50 |

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

PIERCE SIM WEI ZHI
 BLK 22 CHOA CHU KANG GROVE #07-53
 SINGAPORE 688213

Contact : 98713154, 81837891

TAX INVOICE

Repair Code : CLM15675

Date in : 28/09/2022

Vehicle Num. : SNB6140M

Model : MINI COOPER S COUNTRYMAN 1.6 AT HID TC FWD

Chassis/Eng# : WMWZC32010WM94554/A194J069N18B16A

| | | | | | |
|--|-----------------|---|---------|----------------|-------------------|
| FRONT LH HEADLAMP WASHER COVER | <i>Neu</i> | 1 | 27.25 | <i>x.</i> | 27.25 |
| FRONT LH HEADLAMP WASHER PUMP | <i>included</i> | 1 | 93.85 | <i>✓</i> | 93.85 |
| FRONT LH KNUCKLE ARM | <i>Repd</i> | 1 | 518.50 | <i>✓</i> | 518.50 |
| FRONT LH KNUCKLE ARM BEARING | <i>Repd.</i> | 1 | 477.00 | <i>✓</i> | 477.00 |
| FRONT LH LOWER ARM | <i>Best</i> | 1 | 348.70 | <i>✓</i> | 348.70 |
| FRONT LH LOWER ARM BALL JOINT | <i>Best</i> | 1 | 132.15 | <i>✓</i> | 132.15 |
| FRONT LH SHOCK ABSORBER | <i>Neu</i> | 1 | 336.50 | <i>+</i> | 336.50 |
| FRONT LH SHOCK ABSORBER MOUNTING | <i>Neu</i> | 1 | 194.70 | <i>+</i> | 194.70 |
| FRONT LH SPORT RIM | <i>Lt</i> | 1 | 1542.60 | <i>800(SN)</i> | 1,542.60 |
| FRONT LH STEERING TIE ROD END | <i>Neu</i> | 1 | 232.10 | <i>+</i> | 232.10 |
| FRONT SUPPORT PANEL | <i>included</i> | 1 | 722.55 | <i>✓</i> | 722.55 |
| WASHER TANK | <i>Delvd</i> | 1 | 167.45 | <i>✓</i> | 167.45 |
| WASHER TANK MOTOR | <i>Repd.</i> | 1 | 95.30 | <i>✓</i> | 95.30 |
| Subtotal before discount | | | | | 12,800.20 |
| Percentage discount 5% | | | | | 640.01 |
| Sub-total 1 | | | | | 12,160.19 |
| FRONT BONNET 3D STICKER | <i>Neu</i> | 1 | 450.00 | <i>250</i> | 450.00 |
| FRONT BONNET INSULATOR MAT CLIPS - SET | <i>Neu</i> | 1 | 50.00 | <i>20</i> | 50.00 |

8 235 40
lem 10% : 741186
S.N : 800

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
 2 Kaki Bukit Ave 2
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
 E-Mail : sales@n51.com.sg
 Company Reg. No. : 200714616M
 GST Registration No. : 200714616M

PIERCE SIM WEI ZHI
 BLK 22 CHOA CHU KANG GROVE #07-53
 SINGAPORE 688213

Contact : 98713154, 81837891

TAX INVOICE

Repair Code : CLM15675

Date in : 28/09/2022

Vehicle Num. : SNB6140M

Model : MINI COOPER S COUNTRYMAN 1.6 AT HID TC FWD

Chassis/Eng# : WMWZC32010WM94554/A194J069N18B16A

| | | | |
|--|--------------|--------|---------------------|
| FRONT LH FENDER ARCH GARNISH CLIPS - SET <i>mm</i> | 1 | 40.00 | 20 40.00 |
| FRONT LH FENDER INNER SHIELD CLIPS - SET <i>mm</i> | 1 <i>370</i> | 50.00 | 30 50.00 |
| FRONT LH TYRE <i>mm</i> | 1 | 450.00 | x 450.00 |
| RADIATOR COOLANT <i>mm</i> | 1 | 60.00 | 50 60.00 |
| Subtotal before discount | | | 1,100.00 |
| Percentage discount 0% | | | 0.00 |
| Sub-total 2 | | | 1,100.00 |
| Parts-total | | | 13,260.19 |

LABOUR

| | | |
|---|------|------------------|
| To remove, reinstall air con parts, vacuums, refill air con gas. (to FR) | 120 | 150.00 |
| To remove, reinstall electrical wiring harness, check lighting. (to FR) | 30 | 60.00 |
| To reset system after repair works | x | 250.00 |
| To remove, reinstall front suspension undercarriage parts. (to FR) | 2040 | 200 |
| To road test driving, check and resetting wheel alignments system. | 80 | 150.00 |
| To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident. | 650 | 1,000.00 |
| To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident. | 900 | 1,200.00 |
| To apply anti-rust chemical on repaired and replaced panel. | 60 | 100.00 |
| Labour Total | | 3,160.00 |
| Parts & Labour Total | | 16,420.19 |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

page 3
09/09 *8.5K*

Admin Lj
 H/S - 09 Days.
 total: 10621.86
 H/S: 8.5K