

**Automotive Repair Centre Pte Ltd**

CO. Reg. No. : 201312913C

GST Reg. No. : 201312913C

Estimate

38 Woodlands Industrial Park E1

#05-18, Singapore 757700

Tel: 64688834 Fax: 64622278

E-mail: info@automotiverepaircentre.com.sg

ESTIMATE NO. : EST2209-530

DATE : 29-Sep-2022

POLICY NO. :

VEHICLE REG. NO. : SKH9336A

VEHICLE MAKE : MERCEDES BENZ / SLK 200 A

TO Motor Claim Department**China Taiping Insurance (Singapore) Pte. Ltd**

3 Anson Road, #15-00 Springleaf Tower

Singapore 079909

Tel: 6389 6116, Fax: 6222 1033

FOR SURVEYOR**ESTIMATE REPAIR COST**

NO.	DESCRIPTION	QUANTITY	UNIT COST	TOTAL COST
	<u>SPARE PARTS</u>			
1	Rear Bumper	1	\$ 2,820.00	\$ 2,820.00
2	Rear Bumper Retainer RH	1	\$ 50.00	\$ 50.00
3	Rear Bumper Retainer LH	1	\$ 50.00	\$ 50.00
4	Rear Bumper Lower	1	\$ 248.00	\$ 248.00
5	Rear Bumper Tow Cover	1	\$ 80.00	\$ 80.00
6	Rear Reinforcement	1	\$ 700.00	\$ 700.00
7	Rear Sponge	1	\$ 210.00	\$ 210.00
8	Bootlid	1	\$ 2,866.00	\$ 2,866.00
9	Bootlid SLK200 Emblem	1	\$ 120.00	\$ 120.00
10	Bootlid Mercedes Emblem	1	\$ 120.00	\$ 120.00
11	Rear Boot Weatherseal Rubber	1	\$ 250.00	\$ 250.00
12	End Panel Garnish	1	\$ 196.00	\$ 196.00
13	Tail Lamp RH	1	\$ 800.00	\$ 800.00
Total Spare Parts				\$ 8,510.00
	<u>SPECIAL NETT</u>			
14	Reverse Sensors	1	\$ 280.00	\$ 280.00
15	Rear Bumper Clips	10	\$ 5.00	\$ 50.00
Total Special Nett				\$ 50.00
	<u>LABOUR</u>			
16	Remove, Refit, Repair and Replace Accident Affected Parts	1	\$ 750.00	\$ 750.00
17	Spray Paint (Rear Bumper, Bootlid, Rear Reinforcement and End Panel)	1	\$ 1,000.00	\$ 1,000.00
18	Diagnose, Rectify, Calibrate Fault Codes	1	\$ 200.00	\$ 200.00
19	Remove and Replace Reverse Sensors	1	\$ 100.00	\$ 100.00
20	Remove, Align and Refit Rear Exhaust	1	\$ 80.00	\$ 80.00
21	Check and Rectify Electrical Wiring	1	\$ 30.00	\$ 30.00
Total Labour				\$ 2,160.00
Amount Before Excess				\$ 10,720.00
Add GST @ 7%				750.40
Total Amount Payable				\$ 11,470.40

Estimate prepared by: KenGuan

The above is an estimate based on our inspection and does not cover any additional parts or labour which may be required after work has been started. Occasionally, worn or damaged parts are discovered which may not be evident on the first inspection. Because of this, the above price are not guaranteed. Quotation on parts and labour are current and subject to change.