



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CS3/III22007642/Ecy3-1

INDIA INTERNATIONAL INSURANCE PL
64 CECIL STREET
#05-02 IOB BUILDING SINGAPORE 049711

Ref: ~~CS3/III22007642/Ecy3-1~~
Date: ~~11/08/2022~~ 28/09/2022
Code: III2

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SMW 4471Y	Veh. Inspected	SMQ 1774A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	Shovaneswari CARINE KEK	Assign Date	11/08/2022 28/09/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	04/08/2022	Inspection Date	11/08/2022
Survey held at	V-TECH AUTO SERVICE No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.