



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2205414

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 02/09/2022
Reference CS3/III22007642/Ecy3e2
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SMQ 1774A

Bill cancel refer to new invoice No. AC2207132 18/11/2022 \$261.00

Insured Veh. SMW 4471Y

Claim No.

Policy No.

Accident Date 04/08/2022

Inspection Date 11/08/2022

Description	Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	120.00
- First Inspection 11.08.2022 02.48pm	
- Dismantle Inspection 12.08.2022 10.30am	
- After Repair Inspection 16.08.2022 01.00pm	
Merimen Fee	11.00
Subtotal	131.00
GST (7%)	9.17
Grand Total	140.17

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

INDIA INTERNATIONAL INSURANCE PL

INV No. AC2207132

64 CECIL STREET
#05-02 IOB BUILDING
SINGAPORE 049711

INV Date 18/11/2022
Reference CS3/III22007642/Ecy3e2-1
Code III2

PROFESSIONAL SERVICE FEE

Vehicle No. SMQ 1774A
Insured Veh. SMW 4471Y
Claim No. MFL2022D0004319
Policy No. D20MFL0005826_01
Accident Date 04/08/2022
Inspection Date 11/08/2022

Description	Total
Survey Inspection	250.00
Resurvey Inspection	
Digital Photographs	
Transportation	
Merimen Fee	11.00
Note: Pls discard Inv.AC2205414 dated 02/09/2022 \$140.17	
Subtotal	261.00
GST (7%)	18.27
Grand Total	279.27

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

KHM