

Date: 29/09/2022

Vehicle No: SNC4339R

Model: HYUNDAI AE IONIQ HEV 1.6

Chassis: KMHC851CVMU260891-2021

Reg.Year: 2021

Third Party Insurer: LONPAC

Third Party Veh No: XE966C

Date of Accident: 13/07/2022

Estimator: TING AN

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER	1		~ \$576.00
2	REAR BUMPER SIDE BRACKET RH	1		~ \$55.00
3	REAR FENDER RH	1		~ \$1,768.00
4	REAR FENDER INNER SHIELD RH	1		~ \$88.00
5	REAR FENDER QUARTER GARNISH COVER ASSY RH	1		~ \$108.00
SUB TOTAL				\$2,595.00
LESS 20%				-\$519.00
PARTS TOTAL				\$2,076.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		~ \$50.00
S/N TOTAL				\$50.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.

\$500.00 ✓

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BUMPER, REAR FENDER RH & ETC.

\$500.00 400/

LABOUR CHARGES TO REMOVE & REFIX REAR FENDER INNER TRIM & CUSHION UPHOLDSTERY SET & ETC. TO EFFECT REPLACE OF REAR FENDER RH.

\$250.00 100/

TO CHECK WIRING & ELECTRICAL SYSTEM.

\$80.00 15/

LABOUR TOTAL \$1,330.00

TING AN

TOTAL \$3,456.00

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 | Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554800
Tel: (+65) 6484 9919 | Fax: (+65) 6481 1893

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

