



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:KITTY TEO		Ref: CC4/ASM22009603/Kpa3q2 Date: 09/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 585M	Veh. Inspected	SMN 2081A
Policy No.	P2459880	Coverage (\$)	0.00
Claim No.	S2M045E8	Excess (\$)	0.00
Assign From		Assign Date	29/09/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA FIT (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2019
Chassis No.	GP51342785	Colour	METALLIC GREY
Odometer	220310 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	185/60 R15	TRIANGLE	9 mm
L/H Front Tyre	185/60 R15	TRIANGLE	9 mm
R/H Rear Tyre	185/60 R15	TRIANGLE	9 mm
L/H Rear Tyre	185/60 R15	TRIANGLE	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE N/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/06/2022	Inspection Date	29/09/2022
Survey held at	MY CAR CONSULTANT PTE LTD 60 JALAN LAM HUAT #05-21 CARROS CENTRE SINGAPORE 737869		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	