

Huat (Meng Kee) Motor Pte Ltd
 #60 Sin Ming Drive, #04-01, #04-02 &
 #07-03, Sin Ming Autocity
 575722
 Insurer Reference: TP-GBF 8545L
 Repairer Reference: 73045
 Date calculated: 28/09/2022 4:25 PM

Full Report
 Registration: SME 2438C
 Printed: 28/09/2022 4:25 PM

Summary Information

Claim Location: Singapore (SG) Work Provider: China Taiping Insurance (Singapore) Pte Ltd
 Printed by: Jenny Lim Currency: SGD
 Claim Reference: TP-GBF 8545L Date of Incident: 14/09/22
 Estimated Repair Time: Hire Car Start:
 Actual Repair Days: Hire Car End:

Vehicle Details

Vehicle Manufacturer: HONDA
 Model: FREED (GB3)
 Sub Model: G
 Model Sheet Number: 35 FD 07
 Registration: SME 2438C
 VIN number:
 Odometer: 55298
 Model Specs
 AIR CONDITIONING FOG LAMPS 1.5 LTR 65 KW TYRES 185/65 HR 15
 TWO COAT METALLIC PREPARE OFF VEHICLE

*Not with hand
 Recovery B4 repair
 3 days
 @ 1146.71*


Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	WU	Price SGD
NO NUMBER	R + R FRONT BUMPER		1.0		4.20
NO NUMBER	R + R FRONT BADGE		1.0		4.20
NO NUMBER	R + R RADIATOR GRILLE TRIM		2.0		8.40
NO NUMBER	R + R LEFT HEADLAMP		2.0		8.40
NO NUMBER	R + R RIGHT HEADLAMP		2.0		8.40
0283	FRONT BUMPER REPAIR		2.0		8.40
0475	L/BONNET HINGE REPAIR		10.0*		42.00
0476	R/BONNET HINGE REPAIR		5.0*		21.00
1009	FRONT PANEL CPL REPAIR		5.0*		21.00
			20. 30.0*		126.00
Labour Cost			Hrs	WU	
Panel / Mechanical Labour			5.80	58.0	243.60
Total of Labour					243.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:



Paint		SYSTEM AZT	Time Basis 10 WU/h	
Code	Description - TWO COAT METALLIC		WU	Price SGD
	FRONT BUMPER REPAIR PAINT PLASTIC		14.0	
	FRONT PANEL CPL SURFACE PAINT		6.0	

Paint Material Per Part		
Code	Description	Price SGD
0283	FRONT BUMPER REPAIR PAINT PLASTIC	40.50
1009	FRONT PANEL CPL SURFACE PAINT	11.21

11,237.70
2,809.43
Less 25%
Sub-total

Labour Cost - Paint		Hrs	WU	Price SGD
Factor	42.00 SGD/h			
Time Paint			20.0	
Preparation Main Work Metal		0.50	5.0	21.00
Preparation Comp. Work Plastic		2.50	25.0	105.00
Total	10 WU/h	5.00	50.0	210.00

Material Cost - Paint		Price SGD
Repair Painting Plastic		40.50
Surface-/Blend Paint		11.21
Material-constant Metal		9.00
Material-constant Plastic		28.60
Total		89.31

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
0431	GRILLE BADGE	75700TF0000	Original		20.00
0414	GRILLE MOULDING	71123SYYZ01	Original	X not Acc CMT	550.00
Savings					0.00
Subtotal					570.00
Fixed Sundry Parts Price					100.00
Total					670.00

ial Calculation

	SGD	SGD
Parts		
Fixed Sundry Parts Price	570.00	
Total Parts	100.00	670.00
Labour Time Base 10 WU/h		
Total 58.0 WU X 42.00 SGD/h		
Total of Labour	243.60	243.60
Paint Work Time Base 10 WU/h		
Labour Cost 50.0 WU X 42.00 SGD/h		
Material Cost	210.00	
Total Paint Including Material	89.31	299.31
Repair Cost Excludes GST		1,212.91
GST (+7.0%)		84.90
Repair Cost Included GST		1,297.81

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.