



Case Details

Case Reference Number : TAX/09/22/2073
 Type of Repair : Accident Repair
 Vehicle Registration Number : SHB1161G

Company Type : Strides Taxi Pte Ltd
 Estimation ID : EST-19449-ID
 Assigned By : Taxi Claims Manager Team

Insurance Company Name : China Taiping Insurance (Singapore) Pte Ltd
 Accident Date and Time : 28/09/2022 01:49 AM
 Vehicle Age(In Months) :-

Documents / Photographs

[View Documents / Photographs](#)

Total Documents: 0

Estimation Details

Spare Part's Cost Detail

BOM Type	Costing Type	Portion	Material Number	Part Name	Qty	SMRT Recommendation			Surveyor Approval			Remarks		
						List Price	List Price(\$)	Dis(%)	Final Price(\$)	Repair/ Replace	Surveyor Quantity		Surveyor Final Price(\$)	Repair/Replace
Standard	Main			DOOR ASM-RR SI -L	1	2,185.04	2,185.04	10.00	1,966.54	Replace	0	0	Not Give	
Standard	Main			PANEL-BODY SI OTR-L	1	1,747.82	1,747.82	10.00	1,573.04	Replace	0	0	Not Give	
Standard	Main			STICKER ELECTRIC (LOGO	1	21.60	21.60	0.00	21.60	Replace	0	0	Not Give	
Standard	Main			LINER ASM-RR W/H PNL - LH	1	83.72	83.72	10.00	75.35	Replace	1	75.35	Replace	Di ✓
Standard	Main			FASCIA-RR BPR	1	758.48	758.48	10.00	682.63	Replace	1	682.6	Replace	By ✓
Standard	Main			FASCIA-RR BPR LWR	1	230.68	230.68	10.00	207.61	Replace	1	207.6	Replace	Pd ✓
Standard	Main			FINISHER-RR BPR - LH	1	47.42	47.42	10.00	42.68	Replace	1	42.68	Replace	Pd ✓
Standard	Main			BRACKET ASM-RR BPR FASCIA SI-L	1	29.85	29.85	10.00	26.87	Replace	1	26.87	Replace	Di ✓
Standard	Main			BRACKET-RR BPR FASCIA SI MTG - LH	1	46.08	46.08	10.00	41.47	Replace	0	0	Check	
Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) -	1	13.20	13.20	10.00	11.88	Replace	0	0	Surveyor Total	1,067.81
									Total Spare Part Cost	6,082.12				
									Lump Sum Discount (%)	0.00			Lump Sum Dis (%)	0
									Final Spare Part Cost	6,082.12			Final Sur Total	1,067.81

S.N	Standard BOM Type	Main Costing Type	Portion	Material Number	LH SMRT Recommendation BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - CTE	Qty	12.90 List Price Per Unit(\$)	12.90 List Price(\$)	10.00 Dis(%)	11.61 Final Price(\$)	Replace Repair/ Replace	Surveyor Quantity	Surveyor Approval		Remarks
													Surveyor Final Price(\$)	Check Repair/ Replace	
1	Standard	Main			BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST CONT SEN) - CTE	1	12.90	12.90	10.00	11.61	Replace	0	0	Not Give	✓
	Standard	Main			BRACKET-RR BPR FASCIA LWR MTG - LH	1	12.80	12.80	10.00	11.52	Replace	0	0	Check	✓
	Standard	Main			BOLT/SCREW-FRT W/H LNR RET	10	0.52	5.20	10.00	4.68	Replace	0	0	Check	✓
	Standard	Main			BAR ASM-RR BPR IMP	1	339.76	339.76	10.00	305.78	Replace	0	0	Check	✓
	Standard	Main			LAMP ASM-TAIL(BODY SI) - LH	1	764.08	764.08	10.00	687.67	Replace	0	0	Not Give	✓
	Standard	Main			LAMP ASM-TAIL(LID SI) - LH	1	407.68	407.68	10.00	366.91	Replace	0	0	Not Give	✓
	Standard	Main			LAMP ASM-RR FOG - LH	1	36.30	36.30	10.00	32.67	Replace	1	32.67	Replace	✓ <i>CM</i>
Total Spare Part Cost										6,082.12	Surveyor Total		1,067.81		
Lump Sum Discount (%)										0.00	Lump Sum Dis (%)		0		
Final Spare Part Cost										6,082.12	Final Sur Total		1,067.81		

Labour's Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO REPAIR REAR PORTION LH	1,800.00	250.00	
Total:			1,800.00	250.00	

Spray Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO RESPRAY REAR BUMPER	428.00	220	
2	Main	TO RESPRAY REAR FENDER LH	428.00	0	
3	Main	TO RESRAY REAR DOOR LH	428.00	0	
Total:			1,284.00	220.00	

Other Cost Detail

S.No.	Costing Type	Job Scope	SMRT Recommendation(\$)	Surveyor Adjustment(\$)	Remarks
1	Main	TO WASH AND VACUUM	60.00	0	
2	Main	TO CHECK WRING AND SYSTEM FUNCTION	120.00	20	
3	Main	TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0	
4	Main	TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	50	
5	Main	TO REPLACE SUNDRY PARTS	100.00	0	
6	Main	TO CHECK & RESET SYSTEM FUNCTION	350.00	150	
7	Main	ISOLATED OF (EV) (NET)	150.00	150	
Total:			1,000.00	370.00	

Summary

	Estimator Assesment(\$)	Surveyor Assesment(\$)
Total Spare Part Detail	6,082.12	1,067.81
Total Labour Cost	1,800.00	250.00
Total Spray Painting	1,284.00	220.00
Other	1,000.00	370.00
Overall Total	10,166.12	1,907.81
Lump Sum Repair Option		<input type="checkbox"/>
Lump Sum Total	0.00	1,907.81

Surveyor Approved Amount	1,907.81
No of Repair Days*	6
Remarks	<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> To resurvey before/after spray painting To display damaged part(s) during resurvey Parts prices are subject to confirmation Third party survey is on a "Without Prejudice" basis No illegal modification(s) is allowed Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p> <input type="checkbox"/> PART BY PART / Before paint photo FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : </p> <p> Acknowledged by Repairer Signature: Kenneth Kong (LKK) Date: </p>
Surveyor Name	Kenneth Kong (LKK)
Signature	

Save Clear