

**Section A - Accident Details**

Registration Number	SHB1161G
Case Reference Number	TAX/09/22/2073
Registration Date	16/9/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	KHOO KEH HOCK
Type of Accident	Head to Rear
Accident Date and Time	28/9/2022 9:49 AM
Accident Reported Date and Time	28/9/2022 10:52 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116387
Special Instruction to ARC, if any	REAR LEFT PORTION / TP
Prepared Date and Time	28/9/2022 1:03 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

**Section B - Summary of Repair Estimates**

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,400.00	\$450.00
Total Spray Cost	\$1,514.00	\$590.00
Total Spare Part Cost	\$6,387.90	\$1,373.59
Total Other Cost	\$1,000.00	\$370.00
<b>TOTAL COST</b>	<b>\$11,301.90</b>	<b>\$2,783.59 (P/P)</b>
<b>Lump Sum Total</b>	<b>\$0.00</b>	<b>\$0.00</b>
Number of Repair Days	8.0	3.0
Prepared / Adjusted By	<b>Boon Chew Tay</b>	<b>Kenneth Kong (LKK) / China Taiping</b>
ARC / Surveyor Sign Off Date	<b>30/09/2022 3:44 PM</b>	<b>30/09/2022 3:10 PM</b>
Signature		
Remarks	Initial 6 days / sup 2 days / total 8 days	PART BY PART / Before paint photo ,FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com

**Section C - Quotation and Accident Invoice Details**

<b>Quotation Number</b>	QN-2301-0076	<b>Invoice Number</b>	
<b>Quotation Date</b>	11.01.2023	<b>Invoice Date</b>	
<b>Invoice Amount</b>		<b>Prepared Date</b>	

**Section D - Details of Repair Estimates**

<b>Part 1 - Labour Works</b>		
<b>Job Scope</b>	<b>Quotation from AR</b>	<b>Adjusted by Surveyor, if applicable</b>
TO REPAIR REAR PORTION LH	\$1,800.00	\$250.00
TO REPAIR REAR FENDER LH	\$300.00	\$100.00
TO REPAIR REAR END PANEL	\$300.00	\$100.00
<b>Total Labour</b>	<b>\$2,400.00</b>	<b>\$450.00</b>

<b>Part 2 - Spray Painting &amp; Panel Beating Related Works</b>		
<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO RESPRAY REAR PANEL	\$230.00	\$150.00
TO RESPRAY REAR BUMPER	\$428.00	\$220.00
TO RESPRAY REAR FENDER LH	\$428.00	\$220.00
TO RESRAY REAR DOOR LH	\$428.00	\$0.00
<b>Total Spray Painting &amp; Panel Beating</b>	<b>\$1,514.00</b>	<b>\$590.00</b>

<b>Part 3 - Other Costs - Accident and Accident Repair Related Expense</b>		
<b>Job Scope</b>	<b>Quotation from ARC</b>	<b>Adjusted by Surveyor, if applicable</b>
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
<b>Total Other Costs</b>	<b>\$1,000.00</b>	<b>\$370.00</b>

<b>Part 4 - Spare Parts / Material Usage</b>										
<b>Part Number</b>	<b>Portion</b>	<b>Stock Number</b>	<b>Part Name</b>	<b>Quantity</b>	<b>List Price (\$)</b>	<b>Discount (%)</b>	<b>Final Price (\$)</b>	<b>Estimator Approved</b>	<b>Surveyor Approved</b>	
		10380137-SEPP	DOOR ASM-RR SI -L	0.00	\$2,185.04	0.00	\$0.00	Replace	Not Given	X
		10345435-SEPP	PANEL-BODY SI OTR-L	0.00	\$1,747.82	0.00	\$0.00	Replace	Not Given	X
			STICKER ELECTRIC ( LOGO	0.00	\$21.60	0.00	\$0.00	Replace	Not Given	X
		10909176	LINER ASM-RR W/H PNL - LH	1.00	\$83.72	10.00	\$75.35	Replace	Replace	√ dis
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	10.00	\$682.63	Replace	Replace	√ bt
		10751490	FASCIA-RR BPR LWR	1.00	\$230.68	10.00	\$207.61	Replace	Replace	√ dd
		10359002	FINISHER-RR BPR - LH	1.00	\$47.42	10.00	\$42.68	Replace	Replace	√ dd
		10465723	BRACKET ASM-RR BPR FASCIA SI-L	1.00	\$29.85	10.00	\$26.87	Replace	Replace	√ dis

X } nn  
X  
X  
√ dis  
√ bt  
√ dd  
√ dd  
√ dis

**STRIDES Accident Vehicle Repair Estimates**

<b>STRIDES Automotive Services Pte Ltd</b>
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 11/01/2023

User ID : PohSuan

	10326369	BRACKET-RR BPR FASCIA SI MTG - LH	0.00	\$46.08	0.00	\$0.00	Replace	Check	X
	10371766	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$13.20	0.00	\$0.00	Replace	Check	X
	10371768	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$12.90	0.00	\$0.00	Replace	Check	X
	10371790	BRACKET-PARK DIST CONT SEN(BRACKET-PARK DIST	0.00	\$12.90	0.00	\$0.00	Replace	Not Given	X
	10449047	BRACKET-RR BPR FASCIA LWR MTG - LH	0.00	\$12.80	0.00	\$0.00	Replace	Check	X
	90003410	BOLT/SCREW-FRT W/H LNR RET	0.00	\$0.52	0.00	\$0.00	Replace	Check	X
	10327894	BAR ASM-RR BPR IMP	0.00	\$339.76	0.00	\$0.00	Replace	Check	X
	10587409	LAMP ASM-TAIL(BODY SI) - LH	0.00	\$764.08	0.00	\$0.00	Replace	Not Given	X
	10587411	LAMP ASM-TAIL(LID SI) - LH	0.00	\$407.68	0.00	\$0.00	Replace	Not Given	X
	10726676	LAMP ASM-RR FOG - LH	1.00	\$36.30	10.00	\$32.67	Replace	Replace	√
<b>Total</b>				<b>\$6,750.83</b>		<b>\$1,067.81</b>			

} nn  
} nn  
√ cra

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
		10327894	BAR ASM-RR BPR IMP	1.00	\$339.76	10.00	\$305.78	Replace	Replace
<b>Total</b>					<b>339.76</b>		<b>305.78</b>		

√ bt

1,373.59  
+ 450.00  
+ 960.00  

---

2,783.59