

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672



Date Generated : 29/10/2022

User ID PohSuan

Section A - Accident Details

Registration Number	SHC4172A
Case Reference Number	TAX/09/22/2076
Registration Date	12/12/2017
Company Type	Strides Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	SEE TOH WING HOY
Type of Accident	Side Swipe
Accident Date and Time	28/9/2022 2:50 PM
Accident Reported Date and Time	28/9/2022 3:28 PM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116392
Special Instruction to ARC, if any	TP/RIGHT REAR PORTION
Prepared Date and Time	28/9/2022 4:24 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$400.00
Total Spray Cost	\$756.00	\$400.00
Total Spare Part Cost	\$3,088.70	\$1,083.06
Total Other Cost	\$500.00	\$70.00
TOTAL COST	\$5,020.70	\$1,953.06
Lump Sum Total	\$5,000.00	\$1,950.00 (L/S)
Number of Repair Days	5.0	3.0
Prepared / Adjusted By	Boon Chew Tay	Kenneth Kong (LKK) / AIG
ARC / Surveyor Sign Off Date	29/09/2022 4:43 PM	29/09/2022 1:35 PM
Signature		
Remarks	LUMP SUM REPAIR / AFTER PAINT PHOTOS / FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR Kenneth Kong (LKK) HP : 9691 0663 / Email : kennethkong@lkkauto.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2210-0118	Invoice Number	
Quotation Date	11.10.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$676.00	\$400.00
Total Labour	\$676.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR BUMPER	\$378.00	\$200.00
TO RESPRAY REAR FENDER RH	\$378.00	\$200.00
Total Spray Painting & Panel Beating	\$756.00	\$400.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$20.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$50.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$500.00	\$70.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		65637470 60	LINER, REAR FENDER , RH	0.00	\$151.10	0.00	\$0.00	Replace	Not Given
		65565470 10	PATCH, SIDE PANEL REAR END , RH & LH	0.00	\$37.70	0.00	\$0.00	Replace	Not Given
		61601471 50	PANEL SUB-ASSY, FENDER REAR RH	1.00	\$943.10	100.00	\$0.00	Replace	Repair
		66259470 10	COVER, REAR FLOOR UNDER CENTER	0.00	\$249.10	0.00	\$0.00	Replace	Not Given
		58398470 50	COVER, REAR FLOOR UNDER , RH	0.00	\$189.20	0.00	\$0.00	Replace	Not Given
		81497470 20	COVER, REAR COMBINATION LAMP, RH	0.00	\$69.90	0.00	\$0.00	Replace	Not Given
		81581470 10	LENS & BODY ASSY , RR BUMPER , RH	1.00	\$544.40	10.00	\$489.96	Replace	Replace
		81551472 81	LENS & BODY, REAR COMBINATION LAMP , RH	1.00	\$489.00	10.00	\$440.10	Replace	Replace
		90189060 29	REAR BUMPER GROMMET SCREW	0.00	\$2.20	0.00	\$0.00	Replace	Not Given
		89997301 00	ANTENNA, ELECTRICAL KEY	0.00	\$78.00	0.00	\$0.00	Replace	Not Given
			SENSOR REVERSE	0.00	\$180.00	0.00	\$0.00	Replace	Not Given
		52565479 00	FILLER, RR BUMPER , RH	1.00	\$168.60	100.00	\$0.00	Replace	Repair
		52453470 10	GUARD, RR BUMPER, LOWER	0.00	\$623.50	0.00	\$0.00	Replace	Not Given
		52161160 10	CLIPS PIECE, FRT & RR BUMPER	10.00	\$4.80	25.00	\$36.00	Replace	Replace
		52591470 50	SEAL, RR BUMPER , RH	0.00	\$95.50	0.00	\$0.00	Replace	Not Given
		52575470 40	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given
		52599680 30	STOPPER, RR BUMPER, RH & LH	0.00	\$4.80	0.00	\$0.00	Replace	Not Given

X } nn
X
R
X } nn
X } nn
X
√ broken
√ cracked
X
X } nn
X
R
X nn
√ nec
X } nn
X
X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/10/2022

User ID : PohSuan

		52191470 30	SEAL, RR BUMPER ARM, RH & LH	1.00	\$12.30	25.00	\$9.23	Replace	Replace	✓ nec
		52461470 10	PAD, RR BUMPER, CTR	0.00	\$2.50	0.00	\$0.00	Replace	Not Given	X nn
		52462470 10	PAD, RR BUMPER, RH & LH , 3	2.00	\$4.30	25.00	\$6.45	Replace	Replace	✓ nec
		52462470 20	PAD, RR BUMPER, RH & LH , 2	2.00	\$4.30	25.00	\$6.45	Replace	Replace	✓ nec
		52462470 30	PAD, RR BUMPER, RH & LH , 1	2.00	\$4.30	25.00	\$6.45	Replace	Replace	✓ nec
		52023470 30	REAR BUMPER REINFORCEMENT	0.00	\$360.10	0.00	\$0.00	Replace	Not Given	X nn
		52159479 13	COVER, RR BUMPER ASSY	1.00	\$478.90	25.00	\$359.18	Replace	Replace	✓ broken
Total					\$4,825.00		\$1,353.82			

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

	1,353.82	
	-20%	
	1083.06	L/S \$1,950/-
+	400.00	
+	470.00	
	1,953.06	