

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

INV No.

INV Date

Reference

Code

AC2301887

27/03/2023

HSB

CS3/ASM22009612/Tqy3e2

TAX INVOICE

HSBC LIFE (SINGAPORE) PTE LTD

10 MARINA BOULEVARD

#48-01 MARINA BAY FINANCIAL CENTRE

TOWER 2

SINGAPORE 018983 ATTN: TEO KITTY

PROFESSIONAL SERVICE FEE

Vehicle No. CB 6286G

Insured Veh. SHC 3061T

SOMOARWN Claim No.

Ciaim No.	S2M04B W N	
Policy No.	VFX/P2419138	
Accident Date	28/09/2022	
Inspection Date	13/12/2022	
Description		Total
Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)		100.00
Parts dismantled be	efore repair as per NIMA Protocol (Photo taking + Transport on	

Pre-Repair Survey as per NIMA Protocol 2016 Admt 1 (Photo taking + Transport)	100.00
Parts dismantled before repair as per NIMA Protocol (Photo taking + Transport on 19.12.2022)	
Repaired vehicle before return to claimant as per NIMA Protocol (Photo taking + Transport on 29.12.2022)	
Subtotal	100.00
GST (8%)	8.00
Grand Total	108.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to 'LKK Auto Consultants Pte Ltd'

LKK Auto Consultants Pte Ltd

KHM