

(08/11/13) wef

ASS. REC. BY: marcus

REF:

CS/AG/2209621/UVY3**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: **SMS 1971L**

Policy No.

Claims No. **C10017579/CH**

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value:

RM 5k.

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4
20

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No:

JRD P440

Yr Regn:

08/11/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha 135 LC c.c. 135

Colour:

Black

A/C: Insured / Std / NI / NA

Sp. Reading

81888

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PMYUG0410F0322393

Gen. Cond: Good / Fair / Poor / Burnt

Steering: ~~In order~~ / Jammed / Leaked / Burnt oraffectedBrake: ~~In order~~ / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

70-90-17

R:

80-90-17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

maxxis

Front

Rear

R/Bal.

mm

R/Bal.

mm

L/Bal.

17/09/2022 mm

L/Bal.

mm

D.O.A.

28/09/22

D.O.I.

30/09/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

dr, n/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

mv Rmk.11/10/22 4/5 & 1500 : informed mr Kian (red 5435.22; 78%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 12/10/22-typistDays Of Repair: 4Resurvey No. of Trip: 2

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format : **Merimen**Lump Sum / B.I. (\$ 1500)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$



2015 lc135 v4
RM 4 800
Used
2015

Yesterday,
15:19
Penang



USED 2015 yamaha 135lc lc135 FULL ORI ENJIN 9/10
RM 4 500
Used
2015

Sep 27, 15:30
Johor




USED 2015 yamaha 135lc lc135 FULL ORI ENJIN 9/10
RM 4 500
Used
2015

Sep 27, 15:25
Johor



135LC 5s tahun 2015
RM 6 500
Used
2015

Sep 27, 15:21
Sabah



135LC For sale
RM 4 500
Used
2015

Sep 26, 19:16
Selangor



lc135 v3 65/2
RM 6 500
Used
2015

Sep 26, 15:30
Penang



Yamaha 135LC modified
RM 5 555 RM 4 999
Used
2015

Sep 26, 15:14
Perak




yamaha 135 lc enjin good
RM 5 850
Used
2015

Sep 26, 12:05
Selangor



Yamaha 135LC V3
RM 5 200
Used
2015

Sep 26, 11:26
Kelantan



Yamaha 135 Lc Version3 2015 Model
RM 4 800
Used
2015

Sep 25, 13:49
Kuala Lumpur

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 27-Sep-22

Estimate no.

Plate No. JRD8440

Model. YAMAHA LC135

Limited Repair - \$1500

1168

*Not Authorised
30/09/22
2/5 \$1500/
4 days
the photo after work
90096608*

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
1	FORK SET	\$ 450.00	sent / tw, —	
2	FORK T-UNDER BRACKET	\$180 300.00	sent / tw, —	
3	FRONT SPORT RIM	\$300 350.00	waped —	
4	FRONT FENDER	\$80 180.00	one —	
5	FRONT TYRES SHAFT	\$ 150.00	PNX	
6	FRONT DISC BRAKE	\$ 150.00	11X	
7	CHASIS ALIGNMENT	\$ 500.00	11X	
8	HANDLE BAR	\$182 280.00	Buy —	
9	HANDLE BRACKET	\$ 250.00	PNX	
10	STEERING CONE	\$50 180.00	one —	
11	MIRROR	\$45 120.00	310 —	
12	BRAKE LEVEL	\$ 80.00	one ?	
13	IU UNIT	\$ 155.80	one ?	
14	IU BRACKET	\$30 50.00	Buy —	
15	HEAD LAMP	\$ 150.00	one —	
16	HEAD LAMP STAY	\$ 180.00	one —	
17	INNER PANEL	\$110 180.00	one —	
18	PANEL COVER 1	\$120 150.00	one —	
19	PANEL COVER 2	\$120 120.00	one —	
20	DAY LIGHT SET	\$160 280.00	320 —	
21	FRONT FAIRING RIGHT	\$145 200.00	one —	
22	FAIRING INNER COVER RIGHT	\$80 120.00	one —	
23	FRONT FAIRING LEFT	\$145 200.00	one —	
24	FAIRING INNER COVER LEFT	\$ 120.00	PNX	
25	BODY UNDER COVER	\$ 150.00	PNX	
26	BRAKE PEDAL	\$ 180.00	one —	
27	FRONT FOOTREST BAR	\$115 250.00	Buy —	
28	FRONT FOOTREST RUBBER	\$30 100.00	one —	

*Estimate given are base on visible damages **ONLY** before dismantling of the vehicle*

This is computer generated no signature is required.

ERZAT LEE MOTOR TRADING PTE LTD

SYNERGY@KB, 25 KAKI BUKIT ROAD 4 #03-37 SINGAPORE 417800

REG. NO. 201918537M

EMAIL : enquiry@erzatleemotor.com

Office : 69661751

ESTIMATE COST OF REPAIR

Date: 27-Sep-22

Estimate no. 1168

Plate No. JRD8440

Model. YAMAHA LC135

Surveyor's columns

S/N	DESCRIPTION (s)	PRICE (\$)	REMARK	PRICE (\$)
29	FRONT NUMBER PLATE	\$ 30.00	all 105/N	
30	HANDLE BALANCE	\$ 120.00	cut 30	
31	BASKET	\$ 40 80.00	cut	
32	REAR FOOTREST LEFT	\$ 60 120.00	cut	
33	REAR FOOTREST BASKET LEFT	\$ 200.00	17X	
34	REAR BOX	\$ 450.00	cut 220 S/N	
35	REAR MADGUARD	\$ 150 280.00	cut	
36	REAR NUMBER PLATE	\$ 30.00	cut 12 S/N	
37	REAR FAIRING COVER	\$ 180 320.00	cut	
38	LABOUR	\$ 500.00	300	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Less 10% \$ 770.58

Sub Total : \$ 6,935.22

GST 7% \$ 485.47

Total: \$ 7,420.69

Estimate given are base on visible damages ONLY before dismantling of the vehicle

This is computer generated no signature is required.