



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22009622/Uvy3e2	
			Date: 17/10/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 4569J	Veh. Inspected	SMS 1039D
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2203461/RUC	Excess (\$)	0.00
	Assign From	GRACE TEO	Assign Date	29/09/2022
2. Vehicle Particulars & Condition				
	Make & Model	MERCEDES BENZ GLA180 (A)	c.c	1595
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	WDC1569422J677596	Colour	BLACK
	Odometer	35299 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/50 R18	CONTINENTAL	8 mm
	L/H Front Tyre	235/50 R18	CONTINENTAL	8 mm
	R/H Rear Tyre	235/50 R18	CONTINENTAL	8 mm
	L/H Rear Tyre	235/50 R18	CONTINENTAL	8 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	27/09/2022	Inspection Date	29/09/2022
	Survey held at	39 defu lane 12		
	Repairer	ZOOM AUTOWERKS PTE LTD		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days	