

ASS. REC. BY:

REF:

C72/ 22009626/KW

802.11ac

1000Mbps

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MY

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

03

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Belvin

Date / Time

Action / Instruction

Veh No:

SLG 1943R Yr Regn: 06.17

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mit Lancer

c.c

1590

Colour

M. Blue

A/C:

Insured / Std / NI / NA

Sp. Reading

31801

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JMY SRC Y1AGUA 006903

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/80R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

P

mm

R/Bal.

P

mm

L/Bal.

P

mm

L/Bal.

P

mm

D.O.A.

4/9/22

D.O.I.

5/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S R

The UIC / Chassis frame / Body Structure affected due to collision.

OPC

17/02/2023 Finalise L/S \$1,300 @ 03 DAYS (RED 2,748.00 / 68%)

Date/Time, File Pass to?

17/02/2023

Typist

Date/Time, File Return to?

2)



: Prell. Report



: Final Report

Days Of Repair:

3

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

Report Format: TP

Lump Sum / I.B.I: (\$ L/S \$1,300