



Mercedes-Benz

Cycle & Carriage
Industries Pte Limited
Authorised Dealer
Company No. 196400367W
GST Reg No. MR-8500111-X

Finalization

ESTIMATE FOR SJZ8050Y

Singapore Civil Defence Force

Att:Accident Claims Officer
Att:Ralf Tay Gim Chye
91 Ubi Avenue 4
Singapore 408827

Steve

Vehicle & Document Information

WIP No 59802
Reg No/Reg Date SJZ8050Y / 01/04/2022
Date In/Mileage 25/10/2022/ 9596
Chassis No W1K2130532B044110X
Engine No 27492032014019
Make/Model MB/E 300 e SEDAN
Colour/Trim 021 197 Obsidian Bl/ 042 214 Leather Nut

Account No	Terms	Date/Time Printed	CSE	Operator	
CTP00001	Cash	27/10/2022/ 17:23	AQ	305 / Alan Quek Ai Lun	
Description of Goods / Services		Qty	Unit Price	Disc%	Amount

M BPNSUN

POLICY NO/ACC DATE :999996111 // 20-09-2022

DRIVE IN:21-09-2022 // TP CAR NO:YN4126A (SCDF)

DATE IN/DATE SURVEY:25-10-2022 // LKK STEVE

BY/AUTHORIZED ON :RALF TAY GIM CHYE // 05-10-2022

A BPILAB

USE XENTRY TO CHECK CONTROL UNITS & RESET MEMORY TO
STANDARD SETTINGS.NETT

A BPILAB

REMOVE & REPAIR REAR BUMPER

A BPIRES

RESPRAY REAR BUMPER

X REAR BUMPER BOTTOM PANEL

X REAR BUMPER BOTTOM PANEL GARNISH

1.00

336.57

15.00

286.08

1.00

362.74

15.00

308.33

Alan Quek

Cycle & Carriage Industries Pte Ltd

Body Care & Repair Center

DID: 6771 4377 HP: 9186 5112 Fax: 6872 1272

Email: alan.quek@cyclecarriage.com.sg

Confirmed & accepted by

Nett 2,734.41
7% GST on 2734.41 191.41

Authorized signatory and company stamp

Total Payable 2,925.82

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.

Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Pandan Loop Service Center
188 Pandan Loop
Singapore 128378
Tel: 6777 8388
Fax: 6779 5383
www.mercedes-benz.com.sg



and Mercedes-Benz are trademarks of Mercedes-Benz Group AG