

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0827/2022/EQ
DATE : 24-Sep-22
WIP : 43182

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/09/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS ANG HUILING (HONG HUILING)
ADDRESS : BLK 99A LORONG 2 TOA PAYOH
#10-35
SINGAPORE 310099
TELEPHONE : HP +65 91275170
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210053172
VEHICLE NO : **SKN 2571 B**
MODEL CODE : AUDI Q3 SPORTBACK 1.4 TFS
MODEL YEAR : 27/5/2021
ENGINE NO : CZD C37045
CHASSIS NO : WAUZZZF37M1100354
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 22-Sep-22
PLACE OF ACCIDENT : MAS BUILDING CARPARK, PARSI ROAD CARPARK

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 2571 B

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	✓
2	TO RENEW 1/4 GLASS TO FACILITATE RENEWAL OF LHS REAR FENDER.	S/N \$	300.00	✓
3	TO INSTALL SOLAR FILM FOR 1/4 GLASS.	S/N \$	400.00	✓
4	TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY.	S/N \$	1,600.00	✓
5	TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, CD PILLAR TRIMS, LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC.	S/N \$	1,600.00	✓
TOTAL LABOUR CHARGES		:	\$ 4,260.00	

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SKN 2571 B

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO REMOVE AND TRANSFER LHS REAR DOOR'S MULTI-LOCK SYSTEM AND POWER WINDOW DEVICES. INSPECT FOR DAMAGES.	S/N \$ 400.00	280
7	TO DISMANTLE AND RENEW REAR BUMPER AND LHS REAR DOOR. TO CUT OUT AND WELD LHS REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL PARTS REMOVED.	\$ 8,000.00	3500.
8	TO RESPRAY REAR BUMPER, LHS REAR FENDER, LHS REAR DOOR, DOOR COVER, DOOR HANDLE, ROOF CHANNEL, LHS SILL PANEL, DRAIN CHANNEL, DOOR ENTRANCES, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 3575 7,500.00	3025 Lit Fender: 3.5 Door: 1 Bumper: 1
9	TO RENEW LHS REAR TYRE AND CARRY OUT WHEEL ALIGNMENT.	S/N \$ 280.00	X
10	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 20,632.00	3025

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 2571 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Rep's</i>	1	\$ 1,738.00 +	
2	REAR BUMPER SPOILER <i>new</i>	1	\$ 510.00 +	
3	REAR BUMPER ADAPTER - LH <i>3x in</i>	1	\$ 95.00 +	
4	REAR UNDERBODY TRIM - LH	1	\$ 63.00 +	
5	REAR FENDER - LH <i>Dented</i>	1	\$ 3,899.00 ✓	3119.20
6	REAR SIDE WINDOW - LH <i>new</i>	1	\$ 683.00 ✓	546.40
7	REAR WHEEL SPOILER - LH <i>new</i>	1	\$ 44.00 +	
8	REAR SIDE MEMBER TRIM - LH <i>new</i>	1	\$ 189.00 +	
9	REAR DOOR - LH <i>Dented</i>	1	\$ 3,028.00 ✓	2422.40
10	REAR OUTER DOOR SEAL - LH <i>new</i>	1	\$ 151.00 ✓	120.4
11	REAR DOOR CATCH - LH <i>✓ dm</i>	1	\$ 134.00 ?	106.80 ✓
12	REAR SILL PANEL SEAL - LH <i>new</i>	1	\$ 151.00 +	
13	REAR DOOR COVER - LH <i>lit</i>	1	\$ 368.00 ✓	294
14	REAR DOOR HANDLE - LH <i>Rep's</i>	1	\$ 223.00 +	
15	REAR DOOR HANDLE HOUSING - LH <i>Rep's</i>	1	\$ 31.00 +	
16	REAR DOOR HANDLE MOUNTING BAR - LH <i>3x in</i>	1	\$ 182.00 +	
17	REAR DOOR HANDLE BOWDEN CABLE - LH <i>3x in</i>	1	\$ 58.00 +	
18	REAR WINDOW REGULATOR - LH <i>3x in</i>	1	\$ 302.00 +	
19	REAR WINDOW REGULATOR MOTOR - LH	1	\$ 300.00 +	
20	REAR WHEEL HOUSING LINER - LH <i>new</i>	1	\$ 262.00 +	
SUB TOTAL SPARE PARTS		:	\$ 12,411.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SKN 2571 B

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	REAR WHEEL COVER - LH / RH <i>LH Missing, RH nec</i>	2	\$ 1,132.00 ✓	904.80
22	REAR BUMPER GUIDE SECTION - LH <i>? x nn</i>	1	\$ 71.00 ?	X
23	REAR CROSS PANEL - LH <i>nec</i>	1	\$ 445.00 ✓	
24	ACRYLIC SEALANT <i>3</i>	S/N	\$ 180.00 ✓	180
25	CAVITY WAX	S/N	\$ 140.00 ✓	140
26	STONE CHIP <i>2</i>	S/N	\$ 180.00 ✓	180
27	METAL FILLER POWDER <i>2</i>	S/N	\$ 280.00 ✓	280
28	1/4 GLASS SEALANT <i>1</i>	S/N	\$ 100.00 ✓	100
29	LHS REAR TYRE <i>nec nec</i>	S/N	TBC X	X
30	SUNDRIES <i>? ✓ nec</i>		\$ 500.00 ?	182.32 ✓
TOTAL SPARE PARTS		:	\$ 15,439.00	
TOTAL LABOUR CHARGES		:	\$ 20,632.00	
GRAND TOTAL		:	\$ 36,071.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Lj*
SURVEYED DATE : *28/09/22*
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : *Not Authorised, 14 Days.*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT