

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

		Affiliated to Federation Internation	onale Des Experts En Au	utomob	vile CO2/ACM24000450/Ca	
	AXA INSURANCE				CS3/ASM21009450/Gqs	
	8 SHENTON WAY AXA TOWERSING			08/09/202 1 28/09/2022		
			Co	ode:	ASM	
1.		Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	SHC 7061S	Veh. Inspected		FBJ 3326P	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M03GP4	Excess (\$)		0.00	
	Assign From	ANG YVONNE	Assign Date		99/99/202 1 28/09/2022	
2.		Vehicle Part	iculars & Condition	1		
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3.		Condit	ions of Tyres			
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	General Information					
	Accident Date	27/08/2021	Inspection Date		08/09/2021	
	Survey held at					
		25 KAKI BUKIT ROAD 4 #01-75 SYNERGY @ KB SINGAPORE 417800				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.					