

ASS. REC-BY: Tough

REF:

CS/SWR 22009638/1993

ASSIGNMENT

223 Oct

2008, Oct

From: _____ Date: _____

Estimated Cost: _____

OD / TP / NS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: \$4200

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

MichaelVeh No: FBD1095AYr Regn: 2008

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Piaggio Gilera Runner ST 100 198Colour: Black A/C: Insured / Std / NI / NASp. Reading: 9991 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: 2A PM 4640100602347Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: NT / S/Rim / STD A/Rim orTyre Size: F: 120/70R14
R: 140/60R13

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 5 mm R/Bal. 5 mm

L/Bal. _____ mm L/Bal. _____ mm

D.O.A. _____ D.O.I. 5/10/22Survey held at Pave ScooterDes. of Damages Fr / Rear / OS / NS / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Finalise with v/s L/S \$3200, 4 days. (Red \$3118, 49%)

Date/Time, File Pass to?

1) 16/11 Typist

Date/Time, File Return to?

2)

Rep. Format: TPLump Sum / Fee: 3200Days Of Repair: 4Resurvey No. of Trip: 2Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS \$

Photos

Others

PANG SCOOTER SERVICE

Blk 1006 Bukit Merah Lane 2 #01-06 Singapore 159762

Tel : 6271 4618 Fax : 6273 2632

ESTIMATE REPAIR

BIKE NO.: FBD1095A

DOA : 17/09/2022

MAKE/MODEL : PIAGGIO GILERA RUNNER ST 200

S/No	DESCRIPTION	AMOUNT
1	DESCRIPTION	Amount
2	R/H HANDLER END <i>cut</i>	\$ 65.00
3	TOP COWLING <i>cut</i>	\$ 450 650.00
4	R/H SIGNAL LIGHT <i>cut</i>	\$ 98.00
5	LOW COWLING <i>cut</i>	\$ 280 380.00
6	MUFFLER ASSY <i>cut</i>	\$ 980 1,180.00
7	FORK ASSY <i>bt</i>	\$ 680 980.00
8	UNDER BRACKET <i>bt</i>	\$ 280 480.00
9	STEERING CON <i>new</i>	\$ 120 180.00
10	WINDSHIELD <i>cut</i>	\$ 250 285.00
11	METER PANEL COVER <i>un</i>	\$ 135.00
12	REAR BOX <i>cut</i>	\$ 400 485.00
13	SPARY COVER SET <i>dis</i>	\$ 500 800.00
14		4103
15		10% 3692.70
16	TSP <i>X un</i>	\$ 100.00
17	LABOUR <i>300</i>	\$ 500.00
		3692.70
		300
		3992.70
		451 3200*
		4 days
TOTAL :		\$ 6,318.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanfer 97495741
 'un' 5/10/22 @ 350pm
 Resurvey before paint
 Tanfer 97495741
 4 days