

Steve

CS/ICS 22009640/eng3

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SC11 3132K Yr Regn: 16/5/16Type: M/Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Suzuki Forester c.o. 1995Colour: White A/C: Insured / Std / NI / NASp. Reading 51059 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JP 1576 846 072 074

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60R15R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or . _____

Front

Rear

R/Bal. 4 mm R/Bal. 4 mmL/Bal. 4 mm L/Bal. 4 mmD.O.A. 20/9/22 D.O.I. 31/10/22Survey held at Motor Image

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MK-65K

Date/Time, File Pass to?

☐ : Prel. Report

Days Of Repair: _____

1) _____

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

2) _____

Report Format: _____

Lump Sum / L.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee: _____

Transportation: _____

S + R.S. \$ _____

Photos _____

Others _____

TOTAL

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/CHI/0208/2022
DATE : 29-SEP-2022

ECICS LIMITED
10 EUNOS ROAD 8
#09-04A SINGAPORE POST CENTER
S(408600)
TEL : 6337 4779
FAX : 6338 9267

OWNER'S NAME : WAN FOOK KONG
ADDRESS : 1 TOH TUCK TERRACE

TELEPHONE NO : 9723 3657
S(596638)

TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : SI22V04653 LIBERTY
VEHICLE NO : SCH3132E
MODEL CODE : SJGDKK8
MODEL/YEAR : FORESTER 2.0XT AWD CVT
ENGINE NO : FA20A929987
CHASSIS NO : JF1SJGK85GG072024
MILEAGE : 1 KM
DATE IN : 29/09/2022
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : DENNIS LEONG JIA HUI
ACCIDENT DATE : 29/09/2022

Print Date : 29/09/2022
Print Time : 16:39:42

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SCH3132E

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM) AGAINST ECICS LIMITED (GBL2795P)		
2	ZZ/001	DOA:20/09/2022 TIME:1330HRS LOCATION:SLIP RD MOULMEIN RD TWDS THOMSON RD		
3	ZZ/002	REPLACE REAR BUMPER,BUMPER BEAM AND REPAIR END PANEL	1860.00	600
4	ZZ/003	RESPRAY REAR BUMPER,BUMPER BEAM,END PANEL AND TAILGATE	2080.00	520
5	ZZ/004	TO SUPPLY & INSTALL REVERSE SENSOR	300.00	80
6	ZZ/005	APPLY SEALANT TO EFFECTED AREA	200.00	X
7	ZZ/006	TO CONDUCT WATER SEEPAGE TEST	100.00	X
8	ZZ/007	TO CONDUCT (REAR) ANTI RUST COATING 30	580.00	?
9	ZZ/008	SUNDRIES	100.00	20
TOTAL LABOUR CHARGES			5220.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SCH3132E

S/NO	PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
			NETT	LIST	S/NETT	
1	BUMPER FACE R <i>DD</i>	57704SG012	555.00			
2	BRKT SD R RH <i>m</i>	57707SG080	14.80			
3	BRKT SD R LH <i>ne</i>	57707SG090	14.80			
4	BEAM COMPL R EU <i>?</i>	57711SG0219P	296.00			
5	COVER HOOK R <i>CR4</i>	57731SG010NN	13.00			
6	CLIP BMPR X9 <i>ne</i>	909140007	21.60			
7	CLIP 2 PCS <i>ne</i>	909140062	6.00			
SUB TOTAL			899.60	21.60	0.00	0.00
LESS DISCOUNT (NETT-20 % LIST-50 %)			179.92	10.80	0.00	0.00
GRAND TOTAL			719.68	10.80	0.00	0.00
OVERALL TOTAL			730.48			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.
25 LENG KEE ROAD
SINGAPORE 159097

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SCH3132E

TOTAL LABOUR CHARGES	5220.00
TOTAL SPARE PARTS CHARGES	730.48
GRAND TOTAL	5950.48 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME :
SURVEYED DATE :
AUTHORIZED DATE :
EXCESS CLAUSE :
LIABILITY :
REMARKS :

Steve (LKK)
3/10/22, 1.31P
m n
3 Lys
P/P
m BL y

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.