

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	ECICS LTD			Ref:	CS/ICS22009640/y3	
	10 EUNOS ROAD 8 SINGAPORE POS SINGAPORE 4086	Γ CENTRE #09-04A		Date:	30/09/2022	
				Code:	ICS	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	GBL 2795P	Veh. Inspected	l	SCH 3132E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	DMCV2200003H	Excess (\$)		0.00	
	Assign From	SASHE GO	Assign Date		30/09/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5.	5. General Information					
	Accident Date	20/09/2022	Inspection Dat	е	03/10/2022	
	Survey held at	25 Leng Kee Road Singapore 159097				
	Repairer	Repairer MOTOR IMAGE ENTERPRISES PTE LTD				
			marks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					