

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGT 5558L

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	REAR BUMPER (CONSISTENT)	BENT	799.80	799.80
1	REAR BUMPER LH RETAINER -A (CONSISTENT)	DISTORTED	79.70	79.70
1	REAR BUMPER LH RETAINER -B(CONSISTENT)	DISTORTED	68.50	68.50
6	REAR BUMPER CLIPS @\$3.80(CONSISTENT)	NECESSARY	22.80	22.80
1	RH TAILLAMP (CONSISTENT)	BROKEN	348.20	348.20
1	RH TAILLAMP PANEL (CONSISTENT)	TO REPAIR SEE LABOUR	228.10	-
1	REAR RH FENDER (CONSISTENT)	BENT	1,358.70	1,358.70
1	REAR RH FENDER INNER SHIELD (CONSISTENT)	SERVICEABLE	108.50	-
6	REAR RH FENDER INNER SHIELD CLIPS @\$3.50 (CONSISTENT)	NOT NECESSARY	21.00	-
1	REAR RH FENDER AIR POCKET (CONSISTENT)	SERVICEABLE	105.60	-
	LESS 25% DISCOUNT		-785.23	-669.43
			2,355.67	2,008.27
	SPECIAL NETT ITEMS			
1	REAR WINDSCREEN GLASS SEALANT (SN) (CONSISTENT)	NECESSARY	40.00	40.00
1	SET REVERSE SENSOR (SN)(CONSISTENT)	SERVICEABLE	200.00	-
			240.00	40.00
	<u>LABOUR</u>			
	REMOVE & REFIX REAR BUMPER ASSY ,TAILLAMPS ,KNOCK & REPAIR REAR END PANEL ,REAR FENDER INNER PANEL ,CUT ,WELD & REPLACE DAMAGED PARTS.INCLUSIVE OF THE REPAIR OF RH TAILLAMP PANEL .		900.00	700.00
	REMOVE AND REFIX REAR WINDSCREEN GLASS .		120.00	120.00
	REMOVE & REFIX REAR SEATS ,CARPET ,TRIMMINGS ,ETC.		80.00	80.00
	PUTTY & RESPRAY REAR BUMPER ,REAR FENDER ,REAR PANEL ,TAILLAMP PANEL ,WHEEL HOUSE .		900.00	600.00
	RUST PROOFING .		60.00	30.00
			2,060.00	1,530.00
	GRAND TOTAL		4,655.67	3,578.27
		I.	1	

Report Ref No. CC4/ASM22009641/Kpa3q2



Page No.:2 of 2

RECOMMENDED COST OF LUMP SUM REPAIRS		2,850.00
(TO ITS PRE-ACCIDENT CONDITION)		

Report Ref No. CC4/ASM22009641/Kpa3q2

KONG SENG CHEONG

**Licensed Appraiser**