



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2SINGAPORE 018983 ATTN:CYNTHIA		Ref: CC4/ASM22009641/Kpa3q2 Date: 16/06/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	XE 3967E	Veh. Inspected	SGT 5558L
Policy No.	P2074833	Coverage (\$)	0.00
Claim No.	S2M04BXE	Excess (\$)	0.00
Assign From		Assign Date	29/09/2022
2. Vehicle Particulars & Condition			
Make & Model	TOYOTA CAMRY (A)	c.c	2362
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	MR053BK4007035217	Colour	METALLIC BLACK
Odometer	369251 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	MICHELIN	9 mm
L/H Front Tyre	215/60 R16	MICHELIN	9 mm
R/H Rear Tyre	215/60 R16	MICHELIN	9 mm
L/H Rear Tyre	215/60 R16	MICHELIN	9 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	27/09/2022	Inspection Date	29/09/2022
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	