

FIRST AUTOWORKS

Repair Estimate

Date : 29/09/2022

Reference: SGL 6918S

Make: Mazda 6

To Whom It May Concern

Dear Sir,

RE: VEHICLE : SGL 6918S
CHASSIS NO. JM6GJ1072G0222060
ENGINE NO.: PE20703282

Name of insured : Goh Michael
Date of accident.: 23/09/2022

TP Budget Direct.
Veron.

We append hereunder the estimated cost of repairs to be carried out to the above vehicle.

Parts		Part Description	Price (SGD)
No.	Qty		
1	1	FRT BUMPER <i>Delnd</i>	1,311.90 ✓
2	1	FRT BUMPER SPONGE <i>Cracked</i>	92.70 ✓
3	1	FRT BUMPER REINFORCEMENT <i>Bent</i>	659.80 ✓
4	1	FRT BUMPER STIFFENER <i>Neu</i>	169.70 ✓
5	1	FRT BUMPER BRACKET LH <i>Neu</i>	88.50 ✓
6	1	FRT BUMPER SIDE RETAINER LH <i>Delnd</i>	70.50 ✓
7	1	FRT BUMPER INNER COVER LH <i>Neu</i>	76.20 ✓
8	1	FRT BUMPER LOW MLDG LH <i>Neu</i>	108.90 ✓
9	1	FRT BUMPER LOW GRILLE LH <i>Neu</i>	54.60 ✓
10	1	FRT BUMPER LOW CENTRE GRILLE COVER LH <i>Delnd</i>	72.60 ✓
11	1	FRT BUMPER TOW COVER <i>Delnd Neu</i>	96.70 ✓
12	1	FRT NUMBER PLATE BRACKET <i>Neu</i>	111.00 ✓
13	1	FRT GRILLE UPPER PANEL <i>Delnd</i>	504.60 ✓
14	1	FRT GRILLE UPPER PANEL SUPORT <i>Neu</i>	184.00 ✓
15	1	FRT GRILLE UPPER PANEL SUPORT COVER <i>Neu</i>	56.40 ✓
16	1	FRT GRILLE BASE <i>Neu</i>	216.40 ✓
17	1	FRT GRILLE BASE SUPORT <i>Neu</i>	160.70 ✓
18	1	FRT GRILLE BASE SUPORT INNER BRACKET LH <i>2</i>	66.40 ✓
19	2	FRT GRILLE BASE SUPORT INNER BRACKET PIN <i>ap</i>	28.00 ✓
20	1	FRT GRILLE BASE SUPORT LOW BRACKET LH <i>a</i>	38.60 ✓
21	1	FRT GRILLE CHROME MLDG LH <i>Cracked</i>	291.40 ✓
22	1	FRT GRILLE LOGO <i>Neu</i>	88.70 ✓
23	1	FRT GRILLE LOGO BASE <i>Neu</i>	127.80 ✓
24	1	FRT HEADLAMP PANEL LH <i>Neu</i>	161.80 ✓
25	1	FRT HEADLAMP LH <i>Cracked</i>	3,405.60 ✓

Parts Total: 8,243.50

Less 10%: 1,648.70

Total: 6,594.80

640910
5127.28.

1st Autoworks Pte Ltd

23 Kaki Bukit Ave 4, #04-01 (South Wing) Next to Vicom Building, Singapore 415933 Tel : 6844 1985 Fax : 6844 5185

Labour

<u>No.</u>	<u>Labour Description</u>	<u>Price (SGD)</u>
1	To dismantle / renew the accident damaged portion, to panel beating, reshape, straighten, orientate and align repair / replacement parts.	1200.00 <i>300</i>
2	Carry out spray painting on accident affected area. (Frt bumper)	1000.00 <i>250</i>
3	To disconnect wire harness of electrical component to facilitate repairs, reconnect and check electrical function after repair	40.00 <i>30</i>
<i>580</i>		
Labour Total :		2,240.00

Other

<u>No.</u>	<u>Other Description</u>	<u>Price (SGD)</u>
1	Frt Number Plate <i>new</i>	40.00 <i>+</i>
2	Frt Bumper Clip <i>new</i>	35.00 <i>✓</i>
Other Total :		75.00

Total : \$8,909.80
 Gst (7%) : \$623.69
GRAND TOTAL: \$9,533.49

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN T COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER WILL BE INFORMED PRIOR TO ACTION TAKEN. **PARTS PRICES ARE SUBJECT TO CHANGES.**

Yours faithfully

Service Advisor
 Ronnie Tan
 DID: 6844 1985 Fax: 6844 5185

Adrian Li
h/s 03/10/22
03 Days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Supplementary 142.40
total: 5884.68
h/s: 4.71k

Date: 28/10/2022

From: Firstautoworks Pte Ltd

Dear Sirs

RE: VEHICLE NO: SGL 6918S
CHASIS NO: JM6GJ1072G0222060

Supplementary Items

Further to our estimate dated 29.09.2022, we append hereunder the additional Parts & labour required in respect of the repair as carried to the above vehicle for your kind attention.

<u>Parts</u>				
<u>No.</u>	<u>Qty</u>	<u>Description</u>		<u>Amount</u>
1	1	FRT BUMPER LOWER GRILLE	<i>Amcd</i>	178.00

Part Total: 178.00
Less 10%: 17.80
Total: 160.20


20%

142.40

Total: 160.20
7 % GST: 11.21
Grand Total: 171.41

This is only an estimate and should additional work be found necessary to be carried out in the course of repairs, extra materials and labour cost will be charged accordingly. You will be informed prior actions to be taken. **Parts prices are subjected to change.**

Yours faithfully


Service Advisor
Ronnie Tan
DID : 6844 1985 Fax: 68445185

CC :

Fax: