

ASS. REC. BY:

REF:

SNR/ 22009647/K

CS/SMR22009647/Kny3

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_


Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 895k

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No. SLP6261Y Yr Regn: 06 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Honda Step Wgn cc 1496Colour M-Black A/C: Insured / Std / NI / NASp. Reading 127901 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: KP3 1012808Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD A/Rlm orTyre Size: F: 205/30R16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front \_\_\_\_\_ Rear \_\_\_\_\_

R/Bal. 6 mm R/Bal. 4 mmL/Bal. 6 mm L/Bal. 4 mmD.O.A. 27/9/22 D.O.I. 10/10/2022

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Kenneth confirmed lump sum \$4100 and 5 days

(red, \$6662.4, 62%)

Date/Time, File Pass to?

☐ : Prell. Report

1) 18/05/23

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 5Resurvey No. of Trip: 2

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

# Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **MS First Capital Insurance Ltd**  
6, Raffles Quay, #21-00,  
Singapore 048580

Attn : **Motor Claims Department**  
Tel : 65073848  
Fax : 65073849

*Not Notwhite*  
*1/1 Rng &*  
*Recovery After Pain*  
*5 days*

Estimate bill : TT 34 / 22 / TP / WT  
Registration No : SLP6261Y  
Make / model : Honda Stepwgn Spada

Mileage :

Date : 29 / 09 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SDH6260K AND SLP6261Y ALONG  
BALESTIER ROAD OPPOSITE SINGAPORE INDIAN ASSOCIATION ON 27 SEPTEMBER 2022 AT ABOUT 1200HRS.**

|      |                                  |                 |    |          |       |
|------|----------------------------------|-----------------|----|----------|-------|
| 1pc  | Rear boot                        |                 | \$ | 1,702.00 | ✓     |
| 1pc  | Rear boot emblem                 |                 | \$ | 37.00    | ✓     |
| 1pc  | Rear boot 'Stepwgn' designation  |                 | \$ | 146.00   | X     |
| 1pc  | Rear boot 'Spada' designation    |                 | \$ | 1,314.00 | X     |
| 2pcs | Rear boot protector              | (Each \$657.00) | \$ | 160.00   | X     |
| 2pcs | Rear boot protector trim cover   | (Each \$80.00)  | \$ | 289.00   | X     |
| 1pc  | Rear boot lock                   |                 | \$ | 81.00    | X     |
| 1pc  | Rear boot catch                  |                 | \$ | 35.00    | ✓     |
| 1pc  | Rear boot pull handle            |                 | \$ | 207.00   | 7     |
| 1pc  | Rear boot rubber                 |                 | \$ | 1,459.00 | ✓     |
| 1pc  | Rear boot side door              |                 | \$ | 158.00   | 7     |
| 1pc  | Rear boot side door weatherstrip |                 | \$ | 268.00   | X     |
| 2pcs | Rear boot side door hinge        | (Each \$134.00) | \$ | 792.00   | X     |
| 1pc  | Rear end panel                   |                 | \$ | 195.00   | ✓     |
| 1pc  | Rear end panel garnish           |                 | \$ | 206.00   | X     |
| 1pc  | Rear end panel moulding          |                 | \$ | 730.00   | X     |
| 2pcs | Rear bumper                      | (Each \$365.00) | \$ | 172.00   | X     |
| 2pcs | Rear bumper reflector            | (Each \$86.00)  | \$ | 438.00   | 20012 |
| 1pc  | Rear receiver sensor             |                 | \$ | 164.00   | X     |
| 2pcs | Rear bumper side retainer        | (Each \$82.00)  | \$ | 8,553.00 |       |
|      | Sub A total :                    |                 | \$ | 1,710.60 |       |
|      | Less 20% discount :              |                 | \$ | 6,842.40 |       |
|      | A total :                        |                 | \$ |          |       |


## Special net items :

|      |                                   |    |        |   |
|------|-----------------------------------|----|--------|---|
| 1pc  | Rear license smart plate & casing | \$ | 40.00  | X |
| 1set | Rear bumper parking sensor kit    | \$ | 200.00 | X |
|      | B total :                         | \$ | 240.00 |   |

Total amount of Page 1 :

\$ 7,082.40

Tropical Tech Automobile Services

  
( Authorised Signature )  
William Tan



## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

# Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **MS First Capital Insurance Ltd**  
6, Raffles Quay, #21-00,  
Singapore 048580

Attn : **Motor Claims Department**  
Tel : 65073848  
Fax : 65073849

Estimate bill : TT 34 / 22 / TP / WT

Registration No : SLP6261Y

Make / model : Honda Stepwgn Spada

Mileage : Date : 29 / 09 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SDH6260K AND SLP6261Y ALONG  
BALESTIER ROAD OPPOSITE SINGAPORE INDIAN ASSOCIATION ON 27 SEPTEMBER 2022 AT ABOUT 1200HRS.**

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot emblem, rear boot 'Stepwgn' designation, rear boot Spada' designation, rear boot protectors, rear boot protector trim covers, rear boot lock, rear boot catch, rear boot pull handle, rear boot rubber, rear boot side door, rear boot side door weatherstrip, rear boot side door hinges, rear end panel top garnish, rear end panel moulding, rear bumper, rear bumper parking sensors, rear bumper reflectors, rear receiver sensor, rear bumper side retainers.

Heat / weld / cut / renew rear end panel, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear bumper parking sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear boot, rear boot protectors, rear boot side door, rear boot side door hinges, rear end panel, rear bumpers, rear bumper parking sensors.

Balance amount brought from Page 1 :

**Grand final amount :**

\$ 1,500.00 *600*

\$ 100.00 *50*

\$ 80.00 *20*

\$ 200.00 *60*

\$ 1,800.00 *800*

\$ 7,082.40

**\$ 10,762.40**


Tropical Tech Automobile Services

( Authorised Signature )  
William Tan



Date of accident: 27/09/22 Time: 1200 hrs Location: Balestier Rd  
My Vehicle A: SLP6261Y Vehicle B: SHD626CK Vehicle C:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Balestier Rd near Singapore Indian Association. I stopped my vehicle as there was some traffic in front of me. Suddenly a Toyota taxi knocked into my car from behind.

☐ Claim ODI/TP at: ☒ Claim ODI/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :  
Email address :  
& myself :  
Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:

Driver's Signature  
(If driver is not the policyholder,  
Date & Time:

Reporting Centre Police Officer's Signature  
Name:  
NRIC/IN No:



## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

|                                 |                         |
|---------------------------------|-------------------------|
| Date of Submission              | 29/09/2022 15:02 (SGT)  |
| Reported by                     | Driver                  |
| Date of Accident                | 27/09/2022 12:00 (SGT)  |
| Exact Location of Accident      | Balestier Rd, Singapore |
| Additional Location Information | -                       |
| Country/State of Loss           | Singapore               |

### DETAILS OF OWN VEHICLE

|                             |          |
|-----------------------------|----------|
| Vehicle Registration Number | SLP6261Y |
|-----------------------------|----------|

#### INSURED/POLICYHOLDER

|                          |                       |
|--------------------------|-----------------------|
| Is company?              | No                    |
| Name Of Registered Owner | PARTHIBAN MURUGAIAYN  |
| NRIC No                  | SXXXX205H             |
| Email Address            | IJSINGAPORE@YAHOO.COM |
| Mobile Phone No          | (Phone) +65-94777767  |
| Alternative Phone No     | +65-90190418          |

#### VEHICLE PARTICULARS

|                                                                              |                           |
|------------------------------------------------------------------------------|---------------------------|
| Manufacturer                                                                 | Honda                     |
| Model                                                                        | Stepwagon                 |
| Variant                                                                      | STEP WAGON SPADA 1.5 CVT  |
| Exact purpose for which vehicle was being used at time of accident           | Private use               |
| Are you claiming under your own insurance policy for repair to your vehicle? | No - Claiming third party |
| Vehicle Category                                                             | Private car               |
| Transmission                                                                 | Auto                      |
| CC                                                                           | 1496                      |

#### INSURANCE COMPANY

|                                   |                                         |
|-----------------------------------|-----------------------------------------|
| Name of Insurance Company         | Great Eastern General Insurance Limited |
| Policy Number / Cover Note Number | V5001198                                |

#### DRIVER

|                 |                           |
|-----------------|---------------------------|
| Name of Driver  | KRISHNAMOORTHY VENKATESAN |
| Passport No/FIN | GXXXX321K                 |
| Date Of Birth   | 23/03/1989                |
| Occupation      | Indoor                    |