

ASS. REC. BY:

REF:

SNR/ 22009647/K

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 895k

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No. SLP6261Y Yr Regn: 06 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or WagonMake: Honda Stepwgn cc 1496Colour M-Black A/C: Insured / Std / NI / NASp. Reading 127901 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: KP3 1012808Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NI / S/Rlm / STD A/Rlm orTyre Size: F: 205/30R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIG / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front _____ Rear _____

R/Bal. 6 mm R/Bal. 4 mmL/Bal. 6 mm L/Bal. 4 mmD.O.A. 27/9/22 D.O.I. 10/10/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time _____ Action / Instruction _____

Date/Time, File Pass to?

☐ : Prell. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I: (\$

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **MS First Capital Insurance Ltd**
6, Raffles Quay, #21-00,
Singapore 048580

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Not Notwhite
1/1 Rng &
Recovery After Pain
5 days

Estimate bill : TT 34 / 22 / TP / WT
Registration No : SLP6261Y
Make / model : Honda Stepwgn Spada

Mileage :

Date : 29 / 09 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SDH6260K AND SLP6261Y ALONG
BALESTIER ROAD OPPOSITE SINGAPORE INDIAN ASSOCIATION ON 27 SEPTEMBER 2022 AT ABOUT 1200HRS.**

1pc	Rear boot		\$	1,702.00	✓
1pc	Rear boot emblem		\$	37.00	✓
1pc	Rear boot 'Stepwgn' designation		\$	146.00	X
1pc	Rear boot 'Spada' designation		\$	1,314.00	X
2pcs	Rear boot protector	(Each \$657.00)	\$	160.00	X
2pcs	Rear boot protector trim cover	(Each \$80.00)	\$	289.00	X
1pc	Rear boot lock		\$	81.00	X
1pc	Rear boot catch		\$	35.00	✓
1pc	Rear boot pull handle		\$	207.00	7
1pc	Rear boot rubber		\$	1,459.00	✓
1pc	Rear boot side door		\$	158.00	7
1pc	Rear boot side door weatherstrip		\$	268.00	X
2pcs	Rear boot side door hinge	(Each \$134.00)	\$	792.00	X
1pc	Rear end panel		\$	195.00	✓
1pc	Rear end panel garnish		\$	206.00	X
1pc	Rear end panel moulding		\$	730.00	X
2pcs	Rear bumper	(Each \$365.00)	\$	172.00	X
2pcs	Rear bumper reflector	(Each \$86.00)	\$	438.00	20012
1pc	Rear receiver sensor		\$	164.00	X
2pcs	Rear bumper side retainer	(Each \$82.00)	\$	8,553.00	
	Sub A total :		\$	1,710.60	
	Less 20% discount :		\$	6,842.40	
	A total :		\$		


Special net items :

1pc	Rear license smart plate & casing	\$	40.00	X
1set	Rear bumper parking sensor kit	\$	200.00	X
	B total :	\$	240.00	

Total amount of Page 1 :

\$ 7,082.40

Tropical Tech Automobile Services


(Authorised Signature)
William Tan



LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **MS First Capital Insurance Ltd**
6, Raffles Quay, #21-00,
Singapore 048580

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Estimate bill : TT 34 / 22 / TP / WT

Registration No : SLP6261Y

Make / model : Honda Stepwgn Spada

Mileage : Date : 29 / 09 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SDH6260K AND SLP6261Y ALONG
BALESTIER ROAD OPPOSITE SINGAPORE INDIAN ASSOCIATION ON 27 SEPTEMBER 2022 AT ABOUT 1200HRS.**

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot emblem, rear boot 'Stepwgn' designation, rear boot Spada' designation, rear boot protectors, rear boot protector trim covers, rear boot lock, rear boot catch, rear boot pull handle, rear boot rubber, rear boot side door, rear boot side door weatherstrip, rear boot side door hinges, rear end panel top garnish, rear end panel moulding, rear bumper, rear bumper parking sensors, rear bumper reflectors, rear receiver sensor, rear bumper side retainers.

Heat / weld / cut / renew rear end panel, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear bumper parking sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear boot, rear boot protectors, rear boot side door, rear boot side door hinges, rear end panel, rear bumpers, rear bumper parking sensors.

Balance amount brought from Page 1 :

Grand final amount :

\$ 1,500.00 *600*

\$ 100.00 *50*

\$ 80.00 *20*

\$ 200.00 *60*

\$ 1,800.00 *800*

\$ 7,082.40

\$ 10,762.40


Tropical Tech Automobile Services

(Authorised Signature)
William Tan



Date of accident: 27/09/22 Time: 1200 hrs Location: Balestier Rd
My Vehicle A: SLP6261Y Vehicle B: SHD626CK Vehicle C:

SKETCH PLAN



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was driving along Balestier Rd near Singapore Indian Association. I stopped my vehicle as there was some traffic in front of me. Suddenly a Toyota taxi knocked into my car from behind.

☐ Claim ODI/TP at: ☒ Claim ODI/TP at other workshop ☐ Reporting Only

Remarks: Please forward a copy of my efile accident report to:

My workshop :
Email address :
& myself :
Email address :

Note: Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature
Date & Time:

Driver's Signature
(If driver is not the policyholder,
Date & Time:

Reporting Centre Police Officer's Signature
Name:
NRIC/IN No:



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	29/09/2022 15:02 (SGT)
Reported by	Driver
Date of Accident	27/09/2022 12:00 (SGT)
Exact Location of Accident	Balestier Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLP6261Y
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	PARTHIBAN MURUGAIAYN
NRIC No	SXXXX205H
Email Address	IJSINGAPORE@YAHOO.COM
Mobile Phone No	(Phone) +65-94777767
Alternative Phone No	+65-90190418

VEHICLE PARTICULARS

Manufacturer	Honda
Model	Stepwagon
Variant	STEP WAGON SPADA 1.5 CVT
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	Great Eastern General Insurance Limited
Policy Number / Cover Note Number	V5001198

DRIVER

Name of Driver	KRISHNAMOORTHY VENKATESAN
Passport No/FIN	GXXXX321K
Date Of Birth	23/03/1989
Occupation	Indoor