

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M/s : **MS First Capital Insurance Ltd**
6, Raffles Quay, #21-00,
Singapore 048580

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Estimate bill : TT 34 / 22 / TP / WT

Registration No : SLP6261Y

Make / model : Honda Stepwgn Spada

Mileage :

Date : 29 / 09 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SDH6260K AND SLP6261Y ALONG
BALESTIER ROAD OPPOSITE SINGAPORE INDIAN ASSOCIATION ON 27 SEPTEMBER 2022 AT ABOUT 1200HRS.**

1pc	Rear boot		\$	1,702.00	✓
1pc	Rear boot emblem		\$	37.00	✓
1pc	Rear boot 'Stepwgn' designation		\$	146.00	X
1pc	Rear boot 'Spada' designation		\$	1,314.00	X
2pcs	Rear boot protector	0691-50	\$	160.00	X
2pcs	Rear boot protector trim cover	011 mgm (Each \$657.00)	\$	289.00	X
1pc	Rear boot lock	(Each \$80.00)	\$	81.00	X
1pc	Rear boot catch		\$	35.00	✓
1pc	Rear boot pull handle		\$	207.00	✓
1pc	Rear boot rubber		\$	1,459.00	✓
1pc	Rear boot side door		\$	158.00	X
1pc	Rear boot side door weatherstrip		\$	268.00	X
2pcs	Rear boot side door hinge	(Each \$134.00)	\$	792.00	X
1pc	Rear end panel		\$	195.00	✓
1pc	Rear end panel garnish		\$	206.00	X
1pc	Rear end panel moulding		\$	730.00	X
2pcs	Rear bumper	(Each \$365.00)	\$	172.00	X
2pcs	Rear bumper reflector	(Each \$86.00)	\$	438.00	X
1pc	Rear receiver sensor		\$	164.00	X
2pcs	Rear bumper side retainer	(Each \$82.00)	\$	8,553.00	
	Sub A total :		\$	1,710.60	
	Less 20% discount :		\$	6,842.40	
	A total :		\$		

Special net items :

1pc	Rear license smart plate & casing	\$	40.00	X
1set	Rear bumper parking sensor kit	\$	200.00	X
	B total :	\$	240.00	

Total amount of Page 1 :

\$ 7,082.40

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Dr:



Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **MS First Capital Insurance Ltd**
6, Raffles Quay, #21-00,
Singapore 048580

Attn : **Motor Claims Department**
Tel : 65073848
Fax : 65073849

Estimate bill : TT 34 / 22 / TP / WT

Registration No : SLP6261Y

Make / model : Honda Stepwgn Spada

Mileage : Date : 29 / 09 / 2022

**TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SDH6260K AND SLP6261Y ALONG
BALESTIER ROAD OPPOSITE SINGAPORE INDIAN ASSOCIATION ON 27 SEPTEMBER 2022 AT ABOUT 1200HRS.**

Remove and transfer rear boot necessary attachment spart part items.

Remove and transfer rear bumper necessary attachment spart part items.

Remove and refit rear boot, rear boot emblem, rear boot 'Stepwgn' designation, rear boot Spada' designation, rear boot protectors, rear boot protector trim covers, rear boot lock, rear boot catch, rear boot pull handle, rear boot rubber, rear boot side door, rear boot side door weatherstrip, rear boot side door hinges, rear end panel top garnish, rear end panel moulding, rear bumper, rear bumper parking sensors, rear bumper reflectors, rear receiver sensor, rear bumper side retainers.

Heat / weld / cut / renew rear end panel, heat / weld / beating / pull / straighten / align rear chassis frame by Chassis Alignment jack.

Diagnostic and reset rear bumper parking sensor fault error by HHT

To check and refit rear tail lamp wiring harness.

Under coating on rear damaged portion.

Putty / primer application, spray painting rear boot, rear boot protectors, rear boot side door, rear boot side door hinges, rear end panel, rear bumpers, rear bumper parking sensors.

Balance amount brought from Page 1 :

Grand final amount :

\$	1,500.00	6001
\$	100.00	501
\$	80.00	201
\$	200.00	601
\$	1,800.00	8001
\$	7,082.40	
\$	<u>10,762.40</u>	

Tropical Tech Automobile Services

(Authorised Signature)
William Tan

