

振明摩托 CHIN MENG MOTORS

1 Kaki Bukit Ave 6, #01-40 Autobay@Kaki Bukit, Singapore 417883
Tel: 6747-4810 Fax: 6745-5018
cmmotors@singnet.com.sg

ESTIMATE

Our Ref: EST114/22/CIS

Your Ref: To be advised

28-Sep-22

Ergo Insurance Pte Ltd

5 Temasek Boulevard
#04-05 Suntec Tower 5
Singapore 038985

Veron

Attn: Motor Claims Department

Dear Sir/Ms,

Re: Estimate cost of repair to Renault Master no: GBD6628C

Date of accident: 24-09-2022

Parts supply:

1 pc Headlamp L/h	<i>crushed</i>		S\$	933.50	✓
1 pc Front bumper	<i>torn</i>	4286.57		912.82	✓
2 pcs Front bumper retainers @\$157.80	<i>new</i>			315.60	✓
6 pcs Front bumper clips @\$3.50	<i>new</i>			21.00	✓
2 pcs Front bumper brackets @\$105.30	<i>new</i>	3857.91		210.60	✓
1 pc Bonnet	<i>Dented</i>			1,758.50	✓
1 pc Grille	<i>ut</i>			540.05	✓
1 pc Grille emblem	<i>new</i>			120.70	✓
1 pc Grille bracket	<i>new</i>			233.80	✓
				5,046.57	
			Less 10%:	(504.66)	

S/Nett Items

1 pc Headlamp wiremesh L/h (S/Nett)	<i>Dented</i>	120.00	✓
1 pc Bonnet sticker - Certis (S/Nett)	<i>new</i>	100.00	✓
1 pc Front no. plate with cover (S/Nett)	<i>new</i>	45.00	✓
		680	

Labour charges:

To panel beating, welding, removing damaged parts and replacement of the new parts as mentioned above etc.

To respray affected part.

To check wirings

total: 4537.91

L/S: 3-6K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

S\$ 6,136.91

Adrian L
L/S 03/10/22
03 Days