

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/CTI22009658/KVY3Q2**Date:** 07/12/2022REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMPCSNA00041882203

**Claimant Vehicle No :** SMC7158M **Insured Vehicle No :** SJN4210S

Date of Loss: 22/09/2022 Nature of Claim: TP Claim No: SNM22D206813/C02/TOHHS

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMC7158M**

Make & Model: VOLKSWAGEN PASSAT B8, 1.8 TFSI AT 3G24JZ (A) Engine No: CJS285479

Reg. Date: 18/07/2018 (Man. Year: 2018) Chassis No: VVWZZZ3CZJE222642

Colour: Metallic Blue Odometer: 50461 km

Engine Capacity: 1798 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/55 R17 Rear Tyre Size: 215/55 R17

Front Left Side: Pirelli 9 mm Rear Left Side: Pirelli 9 mm

Front Right Side: Pirelli 9 mm Rear Right Side: Pirelli 9 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	7,162.99	3,139.72	4,023.27	56.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,120.00	770.00	350.00	31.25
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>8,282.99</b>	<b>3,909.72</b>	<b>4,373.27</b>	<b>52.80</b>
<b>+ GST 7.00/7.00% (S\$)</b>	579.81	273.68	306.13	52.80
<b>Nett Amount (S\$)</b>	<b>8,862.80</b>	<b>4,183.40</b>	<b>4,679.40</b>	<b>52.80</b>

INSPECTION

Date of Assignment: 30/09/2022

Date Inspected: 30/09/2022 Inspected At: Ah Lim Motor Company (Sin Ming)  
176 Sin Ming Drive #05-12, Sin Ming AutoCare  
Singapore 575721

Estimated Period of Repair: 3.0 days

**Adjuster:** KENNETH KONG**Manager:** VERON CHEN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

### Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 07 Dec 2022)
<b>Parts:</b>	143	VOLKSWAGEN PASSAT B8 1.8 TFSI AT 3G24JZ (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SMC7158M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

### Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT FENDER LH	Bent	1,009.70 FL	*1,009.70 FL
2	1		*FRONT BUMPER	Repair	2,330.70 FL	*- FL
3	1		*HEADLAMP LH	Cracked	2,330.67 FL	*2,330.67 FL
4	1		*FRONT BUMPER LOWER SIDE CHROME MOULDING LH	Dented / Scratched	148.21 FL	*148.21 FL
5	1		*FRONT ALLOY RIM LH	Repair	2,139.60 FL	*- FL
						F=Franchise part. L=ListItemDisc.
					<b>Sub Total (\$\$)</b>	<b>7,958.88 3,488.58</b>
					<b>- List Item Discount on L Items 10.00/10.00% (\$\$)</b>	<b>795.89 348.86</b>
					<b>Total Parts (\$\$)</b>	<b>7,162.99 3,139.72</b>

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO CHECK WIRING AND REFOCUS HEADLAMP	New	20.00	20.00
2	TO DISMANTLE AND REPLACE DAMAGE PARTS ,TO KNOCK ,REPAIR ,ALIGN FRONT AFFECTED AREA	New	550.00	350.00
3	TO SPRAY FRONT BUMPER AND FRONT FENDER LH	New	550.00	400.00
<b>Gross Labour Cost (S\$)</b>			<b>1,120.00</b>	<b>770.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >