

Sng Ah Tee Motor & Panel Service Pte Ltd (Co.Reg.No 200810440N)

Blk 3 Pioneer Road North, #01-18

Singapore 628457

Tel: 6268 6183 Fax: 6268 1429 Email: sngahtee@singnet.com.sg; darren@sngahtee.com; janice@sngahtee.com

INSURER: ERGO Insurance Pte. Ltd. (HQ)**PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	DMPG22007998	Date of Loss:	16/09/2022
Vehicle Reg. No.:	SMZ9986E	Driveable?	
Driver Age/Info:	47 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	CHUA BEE HONG JANE (CAI MEIFENG JANE)	Contact No:	+6598898990
Driver:	CHUA BEE HONG JANE (CAI MEIFENG JANE)		
Make/Model:	VOLVO S60, 1.6 D2 (A)	Vehicle Reg. Date:	27/06/2015
Vehicle Colour:	GREY		
Engine No:	D4162T3269191	Chassis No:	YV1FS84ABF2365948
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO SKETCH PLAN		
Present Location:	SNG AH TEE MOTOR & PANEL SERVICE PTE LTD (PIONEER)		

COST OF CLAIMS	Amount
Parts	4,646.40
Miscellaneous Items	0.00
Labour	1,140.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	5,786.40
+ GST 7.00% (S\$)	405.05
Nett Amount (S\$)	6,191.45

This claim is handled by: JOYCE TAN LAI CHIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 03 Oct 2022)
 Parts: 143 VOLVO S60 1.6 D2 (A) (Catalogue: Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Sng Ah Tee Motor & Panel Service Pte Ltd/SMZ9986E/03/10/2022 09:15
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount	
1	1		*RR BUMPER / <i>CPY</i>	0.00	0.00	*2,016.00 F	✓
2	1		*FRT BUMPER RETAINER LH <i>?</i> X nn	0.00	0.00	*22.00 F	
3	1		*REAR BUMPER UPPER SIDE BRACKET LH <i>?</i> X nn	0.00	0.00	*31.00 F	
4	1		*RR BUMPER CTR BRACKET <i>?</i> X nn	0.00	0.00	*124.00 F	
5	1		*RR BUMPER LOWER SPOILER <i>?</i> <i>CPY</i>	0.00	0.00	*129.00 F	✓
6	1		*RR BUMPER REINFORCEMENT <i>?</i> X nn	0.00	0.00	*592.00 F	
7	10		*REAR BUMPER CLIPS <i>?</i> <i>CPY</i>	0.00	0.00	*50.00 F	✓
8	2		*REAR PARKING AID SENSOR <i>?</i> X nn	0.00	0.00	*260.00 F	
9	1		*REAR EXHAUST PIPE <i>X</i> nn	0.00	0.00	*1,000.00 F	
Sub Total (S\$)						4,224.00	2195
+ Margin on L,N Items 10.00% (S\$)						422.40	+10%
Total Parts (S\$)						4,646.40	2414.50

F=Franchise part.

Sng Ah Tee Motor & Panel Service Pte Ltd/SMZ9986E/03/10/2022 09:15. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items
 are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO KNOCK, WELD, REMOVE & REPLACE ABOVE PARTS	New	250 400.00
2	TO PUTTY & RESRAY PAINTING ON AFFECTED AREAS	New	200 380.00
3	TO REMOVE & REFIT EXHAUST PIPE	New	X 150.00
4	TO CHECK WIRING	New	30.00
5	TO DIAGNOSE AND RESET FAULT CODE	New	100 180.00
580			
Gross Labour Cost (S\$)			1,140.00

Sng Ah Tee Motor & Panel Service Pte Ltd/SMZ9986E/03/10/2022 09:15. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

2994.50

L/S - 2395.60

~~2400~~

=2350

Store (LKK)
 6/10/22, 10.45 AL

OD- L1 N

Exc - ?

R L/S

by P1 y

LKK Auto Consultant's hence notify
 the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Any preliminary demerit(s) must be re surveyed and
 is subject to final approval from Insurance Company

Authorised by Repairer